

State of Colorado Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



ECMC RECEPTION

Receive Date:

08/04/2025

Document Number:

404253883

Off-Location Flowline

The Flowline Report, Form 44, shall be submitted to register, report realignment, report removal from service, provide pre-abandonment notices, or report abandonment of Off-Location Flowlines, Flowline Systems, Produced Water Transfer Systems, or Crude Oil Transfer Lines or Systems as required by the 1100 Series Rules. The Form 44 shall also be submitted to register, report realignment, or report abandonment of Domestic Taps, and to report Grade 1 Gas Leaks from Flowlines per Rules 610 and 906.

Operator Information

ECMC Operator Number: 10633 Contact Person: Fred Kayser
Company Name: CRESTONE PEAK RESOURCES OPERATING LLC Phone: (970) 396-4900
Address: 555 17TH STREET SUITE 3700 Email: fkayser@civiresources.com
City: DENVER State: CO Zip: 80202

Is the Operator a Tier One member of the Utility Notification Center of Colorado (CO811) that participates in Colorado's One Call notification system? Yes [X] No [ ]

OFF LOCATION FLOWLINE

FLOWLINE ENDPOINT LOCATION IDENTIFICATION

Location ID: 470472 Location Type: Production Facilities
Name: SPRAGUE-62N67W Number: 9SWNE
County: WELD
Qtr Qtr: SWNE Section: 9 Township: 2N Range: 67W Meridian: 6
Latitude: 40.154304 Longitude: -104.891727

Description of Corrosion Protection

Crestone pipelines are covered in a protective external coating. Flowlines are subject to thorough inspections and fabrication standards during installation to minimize coating and pipe defects. Crestone maintains a chemical program to reduce internal corrosion. If a flowline is found to lack integrity, Crestone will investigate, report, and remediate any spills in accordance with the 900 series rules.

Description of Integrity Management Program

Crestone flowlines are pressure tested prior to placing flowlines into service. Flowlines are tested on an annual basis in accordance with COGCC 1104 series rules. If a flowline is found to lack integrity, Crestone will investigate the root cause, as well as report and remediate any spills in accordance with the 900 series rules. All repairs will be completed in accordance with COGCC 1102 Series rules.

Description of the construction method used for public by-ways, road crossings, sensitive wildlife habitats, sensitive areas, and natural and manmade watercourses (i.e., open trench, bored and cased, or bored only), if applicable.

N/A

FLOWLINE FACILITY INFORMATION

Flowline Facility ID: 469239 Flowline Type: Wellhead Line Action Type: Abandonment Verification

OFF LOCATION FLOWLINE REGISTRATION

Equipment at End Point Riser: Separator

**Flowline Start Point Location Identification**

Location ID: 336388 Location Type: Well Site   
Name: SPRAGUE-62N67W Number: 9SWNE  
County: WELD No Location ID  
Qtr Qtr: SWNE Section: 9 Township: 2N Range: 67W Meridian: 6  
Latitude: 40.154257 Longitude: -104.893063

Equipment at Start Point Riser: Well

**Flowline Description and Testing**

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 2.000  
Bedding Material: Native Materials Date Construction Completed: 06/14/1999  
Maximum Anticipated Operating Pressure (PSI): 230 Testing PSI:  
Test Date:

**OFF LOCATION FLOWLINE Abandonment Verification**

Date: 05/12/2025

**Abandonment Verification**

The abandoned Off-Location Flowline was located within the jurisdiction(s) of the following local government(s).  
(No Jurisdiction)

**Description of Abandonment Verification:**

The flowline serving the Sprague 32-9 (05-123-19765) was removed in its entirety. Bellholes were dug on average every 80 feet and the line pulled. Once the flowline was removed, all areas that needed it were backfilled and the land surface was graded.

**FLOWLINE FACILITY INFORMATION**

Flowline Facility ID: 469222 Flowline Type: Wellhead Line Action Type: Abandonment Verification

**OFF LOCATION FLOWLINE REGISTRATION**

Equipment at End Point Riser: Separator

**Flowline Start Point Location Identification**

Location ID: 336388 Location Type: Well Site   
Name: SPRAGUE-62N67W Number: 9SWNE  
County: WELD No Location ID  
Qtr Qtr: SWNE Section: 9 Township: 2N Range: 67W Meridian: 6  
Latitude: 40.154257 Longitude: -104.893063

Equipment at Start Point Riser: Separator

**Flowline Description and Testing**

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 2.000  
Bedding Material: Native Materials Date Construction Completed: 02/04/2005  
Maximum Anticipated Operating Pressure (PSI): 320 Testing PSI:  
Test Date:

**OFF LOCATION FLOWLINE Abandonment Verification**

Date: 05/12/2025

**Abandonment Verification**

The abandoned Off-Location Flowline was located within the jurisdiction(s) of the following local government(s).

(No Jurisdiction)

**Description of Abandonment Verification:**

The flowline serving the Sprague 6-4-9 (05-123-22638) was removed in its entirety. Bellholes were dug on average every 80 feet and the line pulled. Once the flowline was removed, all areas that needed it were backfilled and the land surface was graded.

**OPERATOR COMMENTS AND SUBMITTAL**

Comments Form 44 filed to report POST-ABANDONMENT verification. The following flowlines were removed:  
12319765\_FL: services the SPRAGUE 32-9 (05-123-19765)  
12322638\_FL: services the SPRAGUE 6-4-9 (05-123-22638)  
  
Updated GIS data attached.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct and complete.

Signed: \_\_\_\_\_ Date: 08/04/2025 Email: flowlines@civiresources.com

Print Name: Stephany Olsen Title: Sr. Regulatory Analyst

Based on the information provided herein, this Flowline Report complies with ECMC Rules and applicable orders and is hereby approved.

ECMC Approved: \_\_\_\_\_ **Director of ECMC** Date: \_\_\_\_\_

**CONDITIONS OF APPROVAL, IF ANY LIST**

**COA Type**

**Description**

--	--

**ATTACHMENT LIST**

**Att Doc Num**

**Name**

404260803	OFF-LOCATION FLOWLINE GIS SHP
-----------	-------------------------------

Total Attach: 1 Files

**General Comments**

**User Group**

**Comment**

**Comment Date**

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)