

State of Colorado Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



ECMC RECEPTION

Receive Date:

09/30/2024

Document Number:

403463136

Off-Location Flowline

The Flowline Report, Form 44, shall be submitted to register, report realignment, report removal from service, provide pre-abandonment notices, or report abandonment of Off-Location Flowlines, Flowline Systems, Produced Water Transfer Systems, or Crude Oil Transfer Lines or Systems as required by the 1100 Series Rules. The Form 44 shall also be submitted to register, report realignment, or report abandonment of Domestic Taps, and to report Grade 1 Gas Leaks from Flowlines per Rules 610 and 906.

Operator Information

ECMC Operator Number: 10633 Contact Person: James Miller
Company Name: CRESTONE PEAK RESOURCES OPERATING LLC Phone: (720) 984-7460
Address: 555 17TH STREET SUITE 3700 Email: jmiller@civiresources.com
City: DENVER State: CO Zip: 80202
Is the Operator a Tier One member of the Utility Notification Center of Colorado (CO811) that participates in Colorado's One Call notification system? Yes [X] No [ ]

OFF LOCATION FLOWLINE

FLOWLINE ENDPOINT LOCATION IDENTIFICATION

Location ID: 413189 Location Type: Production Facilities
Name: RAY NELSON Number: 44-32
County: WELD
Qtr Qtr: SWSE Section: 32 Township: 2N Range: 68W Meridian: 6
Latitude: 40.089930 Longitude: -105.023710

Description of Corrosion Protection

Crestone pipelines are covered in a protective external coating. Flowlines are subject to thorough inspections and fabrication standards during installation to minimize coating and pipe defects. Crestone maintains a chemical program to reduce internal corrosion. If a flowline is found to lack integrity, Crestone will investigate, report, and remediate any spills in accordance with the 900 series rules.

Description of Integrity Management Program

Crestone flowlines are pressure tested prior to placing flowlines into service. Flowlines are tested on an annual basis in accordance with COGCC 1104 series rules. If a flowline is found to lack integrity, Crestone will investigate the root cause, as well as report and remediate any spills in accordance with the 900 series rules. All repairs will be completed in accordance with COGCC 1102 Series rules.

Description of the construction method used for public by-ways, road crossings, sensitive wildlife habitats, sensitive areas, and natural and manmade watercourses (i.e., open trench, bored and cased, or bored only), if applicable.

N/A

FLOWLINE FACILITY INFORMATION

Flowline Facility ID: 466473 Flowline Type: Wellhead Line Action Type: Out of Service

OFF LOCATION FLOWLINE REGISTRATION

Equipment at End Point Riser: Separator

**Flowline Start Point Location Identification**

Location ID: 413189 Location Type: Well Site   
Name: RAY NELSON Number: 44-32  
County: WELD No Location ID  
Qtr Qtr: SWSE Section: 32 Township: 2N Range: 68W Meridian: 6  
Latitude: 40.089930 Longitude: -105.023710

Equipment at Start Point Riser: Well

**Flowline Description and Testing**

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 2.000  
Bedding Material: Native Materials Date Construction Completed: 05/31/2010  
Maximum Anticipated Operating Pressure (PSI): 500 Testing PSI:  
Test Date:

**OFF LOCATION FLOWLINE Out of Service**

Date: 10/13/2022  Entire Line Removal  Partial Line Removal

**Description of Out of Service:**

The flowline (12330610\_FL) servicing the Ray Nelson 44-32 (05-123-30610) is now out of service as per rule 1102.O.(2). The most recent successful pressure test date is 4/27/2018. This is within 12 months of well's LDOP, per staff guidance.

**FLOWLINE FACILITY INFORMATION**

Flowline Facility ID: 466471 Flowline Type: Wellhead Line Action Type:

**OFF LOCATION FLOWLINE REGISTRATION**

Equipment at End Point Riser: Separator

**Flowline Start Point Location Identification**

Location ID: 413189 Location Type: Well Site   
Name: RAY NELSON Number: 44-32  
County: WELD No Location ID  
Qtr Qtr: SWSE Section: 32 Township: 2N Range: 68W Meridian: 6  
Latitude: 40.089930 Longitude: -105.023710

Equipment at Start Point Riser: Well

**Flowline Description and Testing**

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 2.000  
Bedding Material: Date Construction Completed: 03/22/2010  
Maximum Anticipated Operating Pressure (PSI): Testing PSI:  
Test Date:

**OFF LOCATION FLOWLINE Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification**

Date: \_\_\_\_\_

**Description of Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification:**

\_\_\_\_\_

**FLOWLINE FACILITY INFORMATION**

Flowline Facility ID: 466472 Flowline Type: Wellhead Line Action Type: Out of Service

**OFF LOCATION FLOWLINE REGISTRATION**

Equipment at End Point Riser: Separator

**Flowline Start Point Location Identification**

Location ID: 413189 Location Type: Well Site   
Name: RAY NELSON Number: 44-32  
County: WELD No Location ID  
Qtr Qtr: SWSE Section: 32 Township: 2N Range: 68W Meridian: 6  
Latitude: 40.089930 Longitude: -105.023710

Equipment at Start Point Riser: Well

**Flowline Description and Testing**

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 2.000  
Bedding Material: Native Materials Date Construction Completed: 05/29/2010  
Maximum Anticipated Operating Pressure (PSI): 500 Testing PSI: \_\_\_\_\_  
Test Date: \_\_\_\_\_

**OFF LOCATION FLOWLINE Out of Service**

Date: 10/13/2022

Entire Line Removal  Partial Line Removal

**Description of Out of Service:**

The flowline (12330607\_FL) servicing the Ray Nelson 33-32 (05-123-30607) is now out of service as per rule 1102.O.(2). The most recent successful pressure test date is 3/18/2022. This is within 12 months of well's LDOP, per staff guidance.

**FLOWLINE FACILITY INFORMATION**

Flowline Facility ID: 466475 Flowline Type: Wellhead Line Action Type: \_\_\_\_\_

**OFF LOCATION FLOWLINE REGISTRATION**

Equipment at End Point Riser: Separator

**Flowline Start Point Location Identification**

Location ID: 413189 Location Type: Well Site   
Name: RAY NELSON Number: 44-32  
County: WELD No Location ID  
Qtr Qtr: SWSE Section: 32 Township: 2N Range: 68W Meridian: 6  
Latitude: 40.089930 Longitude: -105.023710

Equipment at Start Point Riser: Well

**Flowline Description and Testing**

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 2.000  
Bedding Material: Native Materials Date Construction Completed: 05/30/2010  
Maximum Anticipated Operating Pressure (PSI): \_\_\_\_\_ Testing PSI: 513  
Test Date: 09/09/2020

**OFF LOCATION FLOWLINE Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification**

Date: 10/21/2020

**Description of Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification:**

Pipe was disconnected from Crestone wellhead and from Crestone separator. Flow line was abandoned in place. Verified by third party inspector. Flowline was flushed with 25bbls fresh water prior to plugging. Line was verified free of hydrocarbons with LEL monitor. Line was cut below ground level. Line was cut below ground and capped.

**FLOWLINE FACILITY INFORMATION**

Flowline Facility ID: 466474 Flowline Type: Wellhead Line Action Type: \_\_\_\_\_

**OFF LOCATION FLOWLINE REGISTRATION**

Equipment at End Point Riser: Separator

**Flowline Start Point Location Identification**

Location ID: 413189 Location Type: Well Site   
Name: RAY NELSON Number: 44-32  
County: WELD No Location ID  
Qtr Qtr: SWSE Section: 32 Township: 2N Range: 68W Meridian: 6  
Latitude: 40.089930 Longitude: -105.023710

Equipment at Start Point Riser: Well

**Flowline Description and Testing**

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 2.000  
Bedding Material: Native Materials Date Construction Completed: 05/29/2010  
Maximum Anticipated Operating Pressure (PSI): 1000 Testing PSI: 520  
Test Date: 09/09/2020

**OFF LOCATION FLOWLINE Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification**

Date: 10/21/2020

**Description of Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification:**

Pipe was disconnected from Crestone wellhead and from Crestone separator. Flowline was abandoned in place. Verified by third party inspector. Flowline was flushed with 25bbls fresh water prior to plugging. Line was verified free of hydrocarbons with LEL monitor. Line was cut below ground level. Line was cut below ground and capped.

**OPERATOR COMMENTS AND SUBMITTAL**

Comments

Form 44 filed to report STATUS CHANGE notification. The following flowline(s) are now out of service:  
12330607\_FL: services the Ray Nelson 33-32 (05-123-30607)  
12330610\_FL: services the Ray Nelson 44-32 (05-123-30610)

All other flowlines will remain as previously reported.  
Updated GIS data attached.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct and complete.

Signed: \_\_\_\_\_ Date: 09/30/2024 Email: flowlines@civiresources.com

Print Name: Stephany Olsen Title: Sr. Regulatory Analyst

Based on the information provided herein, this Flowline Report complies with ECMC Rules and applicable orders and is hereby approved.

ECMC Approved: \_\_\_\_\_ **Director of ECMC** Date: \_\_\_\_\_

**CONDITIONS OF APPROVAL, IF ANY LIST**

**COA Type**

**Description**

--	--

**ATTACHMENT LIST**

**Att Doc Num**

**Name**

403480235	OFF-LOCATION FLOWLINE GIS SHP
403939849	PRESSURE TEST
403939851	PRESSURE TEST

Total Attach: 3 Files

**General Comments**

**User Group**

**Comment**

**Comment Date**

		Stamp Upon Approval
--	--	------------------------

Total: 0 comment(s)