

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



ECMC RECEPTION

Receive Date:

08/06/2024

Document Number:

403878519

Off-Location Flowline

The Flowline Report, Form 44, shall be submitted to register, report realignment, report removal from service, provide pre-abandonment notices, or report abandonment of Off-Location Flowlines, Flowline Systems, Produced Water Transfer Systems, or Crude Oil Transfer Lines or Systems as required by the 1100 Series Rules. The Form 44 shall also be submitted to register, report realignment, or report abandonment of Domestic Taps, and to report Grade 1 Gas Leaks from Flowlines per Rules 610 and 906.

Operator Information

ECMC Operator Number: 10575 Contact Person: James Miller
Company Name: 8 NORTH LLC Phone: (720) 984-7460
Address: 555 17TH STREET SUITE 3700 Email: jmiller@civiresources.com
City: DENVER State: CO Zip: 80202
Is the Operator a Tier One member of the Utility Notification Center of Colorado (CO811) that participates in Colorado's One Call notification system? Yes No

OFF LOCATION FLOWLINE

FLOWLINE ENDPOINT LOCATION IDENTIFICATION

Location ID: 460731 Location Type: Production Facilities
Name: Anderson MB 33-3J, 5, 6 Number:
County: BOULDER
Qtr Qtr: NENW Section: 33 Township: 2N Range: 69W Meridian: 6
Latitude: 40.098422 Longitude: -105.126333

Description of Corrosion Protection

8 North's corrosion procedures are detailed in its Flowline Management SOP. Coating materials will be used that minimize internal and external corrosion, such as internally coated pipe or stainless steel for water service, and externally coated FBE on all buried steel pipe. If flowlines are repaired due to corrosion, 8N will investigate the failure, promptly respond with the appropriate remedial actions and determine the root cause and apply corrective actions as necessary. 8N retains records of its chemical program in the form of Failure Analysis Reports, records of chemical invoices and chemical delivery.

Description of Integrity Management Program

8 North's integrity management program is detailed in its Flowline Management SOP, which covers flowline installation, operation, maintenance, inspection, testing, and repairs. Prior to beginning any project involving flowlines, 8N ensures the project plans, flowline installation, flowline maintenance (including repairs) and all flowline inspection and testing projects meet the requirements of the Flowline Management SOP. All pressure tests on flowlines will be conducted by an independent, third party qualified to do such testing. Precautions shall be taken to protect employees and the general public.

Description of the construction method used for public by-ways, road crossings, sensitive wildlife habitats, sensitive areas, and natural and manmade watercourses (i.e., open trench, bored and cased, or bored only), if applicable.

N/A

FLOWLINE FACILITY INFORMATION

Flowline Facility ID: 461017 Flowline Type: Wellhead Line Action Type: Abandonment Verification

OFF LOCATION FLOWLINE REGISTRATION

Equipment at End Point Riser: Separator

Flowline Start Point Location Identification

Location ID: 321422 Location Type: Well Site
Name: ANDERSON-62N69W Number: 33SEW
County: BOULDER No Location ID
Qtr Qtr: SENW Section: 33 Township: 2N Range: 69W Meridian: 6
Latitude: 40.096711 Longitude: -105.124433

Equipment at Start Point Riser: Well

Flowline Description and Testing

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 2.375
Bedding Material: Native Materials Date Construction Completed: 08/20/1993
Maximum Anticipated Operating Pressure (PSI): 430 Testing PSI: 430
Test Date: 05/04/2017

OFF LOCATION FLOWLINE Abandonment Verification

Date: 05/10/2024

Abandonment Verification

The abandoned Off-Location Flowline was located within the jurisdiction(s) of the following local government(s).

(No Jurisdiction)

Description of Abandonment Verification:

The flowline serving the ANDERSON MB 33-6 (05-013-06415) was removed in its entirety. Bellholes were dug on average every 80 feet and the line pulled. Once the flowline was removed, all areas that needed it were backfilled and the land surface was graded.

FLOWLINE FACILITY INFORMATION

Flowline Facility ID: 461019 Flowline Type: Wellhead Line Action Type:

OFF LOCATION FLOWLINE REGISTRATION

Equipment at End Point Riser: Separator

Flowline Start Point Location Identification

Location ID: Location Type: Well Site
Name: ANDERSON MB-62N69W Number: 33SWNW
County: BOULDER No Location ID
Qtr Qtr: SWNW Section: 33 Township: 2N Range: 69W Meridian: 6
Latitude: 40.096750 Longitude: -105.129170

Equipment at Start Point Riser: Well

Flowline Description and Testing

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 2.375
Bedding Material: Native Materials Date Construction Completed: 08/28/1993
Maximum Anticipated Operating Pressure (PSI): 780 Testing PSI: 776
Test Date: 06/04/2020

OFF LOCATION FLOWLINE Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification

Date: 06/05/2024

Description of Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification:

The flowline serving the ANDERSON MB 33-5 (05-013-06414) will be removed in its entirety via the open trench method. Once the flowline is removed, the trench will be backfilled and the land surface will be graded.

FLOWLINE FACILITY INFORMATION

Flowline Facility ID: 461018 Flowline Type: Wellhead Line Action Type: _____

OFF LOCATION FLOWLINE REGISTRATION

Equipment at End Point Riser: Separator

Flowline Start Point Location Identification

Location ID: 321317 Location Type: Well Site
Name: ANDERSON-62N69W Number: 33NENW
County: BOULDER No Location ID
Qtr Qtr: NENW Section: 33 Township: 2N Range: 69W Meridian: 6
Latitude: 40.098550 Longitude: -105.125750

Equipment at Start Point Riser: Well

Flowline Description and Testing

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 2.375
Bedding Material: Native Materials Date Construction Completed: 02/25/1983
Maximum Anticipated Operating Pressure (PSI): 300 Testing PSI: 300
Test Date: 05/04/2017

OFF LOCATION FLOWLINE Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification

Date: 01/07/2024

Description of Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification:

The flowline serving the ANDERSON MB 33-3J (05-013-06156) will be removed in its entirety via the open trench method. Once the flowline is removed, the trench will be backfilled and the land surface will be graded.

OPERATOR COMMENTS AND SUBMITTAL

Comments

Form 44 filed to report POST-ABANDONMENT verification. The following flowline(s) were removed:
01306415FL: serviced ANDERSON MB 33-6 (05-013-06415)

Updated GIS data attached.
All other related flowlines will remain as previously reported.

The pre-abandonment for 01306415FL was erroneously submitted under Extraction. Duplicate post-abandonment (Doc #403828146) submitted under Extraction to close out pre-abandonment.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct and complete.

Signed: _____ Date: 08/06/2024 Email: flowlines@civiresources.com

Print Name: Stephany Olsen Title: Sr. Regulatory Analyst

Based on the information provided herein, this Flowline Report complies with ECMC Rules and applicable orders and is hereby approved.

ECMC Approved: _____ **Director of ECMC** Date: _____

CONDITIONS OF APPROVAL, IF ANY LIST

COA Type

Description

--	--

ATTACHMENT LIST

Att Doc Num

Name

403878552	OFF-LOCATION FLOWLINE GIS SHP
-----------	-------------------------------

Total Attach: 1 Files

General Comments

User Group

Comment

Comment Date

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)