

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 32D-25D (Mesa 22)

Location #: 335506



Sep 8, 2025 at 5:18:41 PM
+39.495962,-108.165651



Sep 8, 2025 at 5:11:03 PM
+39.495972,-108.165575

Photo # 7114 From entrance to location

Photo # 7115 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 32D-25D (Mesa 22)

Location #: 335506



Photo # 7116 Location




Photo # 7117 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 32D-25D (Mesa 22)

Location #: 335506



Photo # 7118 Location



Photo # 7119 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 32D-25D (Mesa 22)

Location #: 335506




Photo # 7120 Wellhead sign has previous operators name



Photo # 7121 Sign at entrance to location has previous operators name

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 32D-25D (Mesa 22)

Location #: 335506




Photo # 7122 Tank labels have previous operators name



Photo # 7123 PRV vent line on tank burner does not comply with CECMC pressure safety device rules

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC PUCKETT 32D-25D (Mesa 22)

Location #: 335506



Photo # 7124 Tank battery lacks required signage



Photo # 7125 Tank battery lacks required signage