

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/10/2025

Submitted Date:

09/14/2025

Document Number:

698603952

FIELD INSPECTION FORM

Loc ID 303774 Inspector Name: St John, William (Cal) On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10699
Name of Operator: OWN RESOURCES OPERATING LLC
Address: 305 S RIDGE STREET #6279
City: BRECKENRIDGE State: CO Zip: 80424

Findings:

- 2 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Dolezal, Pat	970-332-3585	pat.dolezal@ownresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
253581	WELL	PR	11/12/1993	GW	125-07459	MEKELBURG 6-30	PR

General Comment:

Inspector completed Follow-up inspection 09/10/2025 as required by FIR to ensure corrective actions taken by Operator adequately address and comply with rule requirements cited in 03/06/25 FIR document number 698603300. Operator has submitted FIRR. All corrective actions identified in FIR has been completed.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type	#	corrective date
Gas Meter Run		
Comment: CA completed. Gas meter calibrated 4-7-25.		
Corrective Action:		Date: _____

Venting:

Yes/No		
Comment:		
Corrective Action:		Date: _____

Flaring:

Type	
Comment:	
Corrective Action:	Date: _____

Inspected Facilities

Facility ID: 253581 Type: WELL API Number: 125-07459 Status: PR Insp. Status: PR

Producing Well

Comment:		
Corrective Action:		Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698603978	Inspection photos.	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7236287