

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/08/2025

Submitted Date:

09/08/2025

Document Number:

719500423

FIELD INSPECTION FORM

Loc ID 322313 Inspector Name: Morris, Matthew On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10770
Name of Operator: VISION ENERGY LLC
Address: P O BOX 370
City: IGNACIO State: CO Zip: 81137

Findings:

- 12 Number of Comments
- 7 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Energy, Vision		mollieo@maralexinc.com	
Energy, Vision		mrine20@maralexinc.com	
Energy, Vision		pbechtolt@maralexinc.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210255	WELL	SI	01/01/2022	GW	045-06011	CALF CANYON 14-1	PR

General Comment:

This is a field audit of the location, scout card, and related documents.

On 9/8/2025 at approximately 12:50, Compliance Inspector Matthew Morris conducted an on-site audit at VISION ENERGY LLC, CALF CANYON-66S102W/14SWNW at Location ID #322313 in Garfield County, Colorado.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Incorrect Operator information on wellhead sign.		
Corrective Action:	Update sign to comply with CECMC Signs and Markers Rules.	Date:	10/09/2025

Emergency Contact Number:

Comment:	911	Date:	
Corrective Action:			

Good Housekeeping:

Type	DEBRIS		
Comment:	Debris on location.		
Corrective Action:	Remove debris from location.	Date:	09/16/2025
Type	WEEDS		
Comment:	Weeds present across location.		
Corrective Action:	Remove weeds from location.	Date:	09/16/2025
Type	UNUSED EQUIPMENT		
Comment:	Unused storage tank on location.		
Corrective Action:	Remove unused equipment.	Date:	10/09/2025

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	PIT		
Comment:	Livestock fencing		
Corrective Action:		Date:	

Equipment:

Type: Bradenhead	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:	Separator hatch is open and poses a wildlife entry hazard.		
Corrective Action:	Secure equipment to prevent wildlife entry.	Date:	09/14/2025
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

Type: Gas Meter Run	# 1		
Comment:	Gas meter calibration card has not been updated since 2010.		
Corrective Action:	Calibrate gas metering equipment annually.		Date: 09/19/2025
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 210255 Type: WELL API Number: 045-06011 Status: SI Insp. Status: PR

Producing Well

Comment: Well was producing at time of inspection.

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 02/23/2024 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: Last Bradenhead test performed February 2024.

10/19/2025

Corrective Action: Operator will perform an annual Bradenhead test and submit the data to the Director on a Form 17 or other Director-approved method.

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction						
Gravel						
		Compaction				
		Culverts				
		Gravel				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: _____ Lined: NO Pit ID: 111191 Lat: 39.533944 Long: -108.741836

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment:

Corrective Action:

Date: _____

Fencing:

Fencing Type: Livestock Fencing Condition: Adequate

Comment:

Corrective Action:

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment:

Corrective Action:

Date: _____

Anchor Trench Present: _____ Oil Accumulation: _____ 2+ feet Freeboard: _____

Comment:

Corrective Action:

Date: _____

ECMC Comments

Comment	User	Date
<p>During the audit, the following compliance issues were observed:</p> <ul style="list-style-type: none"> 1) Wellhead sign has incorrect Operator information 2) Debris on location 3) Unused equipment on location 4) Weeds on location 5) Wildlife entry hazards at storage tank and separator 6) Gas meter has not been calibrated since 2010 and well is producing 7) Annual Bradenhead test has not been performed <p>A follow-up on this site audit will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.</p>	<p>morrism</p>	<p>09/08/2025</p>

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404346412	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7224103
719500424	Photo Log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7224102