

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/08/2025

Submitted Date:

09/08/2025

Document Number:

696307988

FIELD INSPECTION FORM

Loc ID: 434923 Inspector Name: PETRIE, ERICA On-Site Inspection: 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 10651
Name of Operator: VERDAD RESOURCES LLC
Address: 1125 17TH STREET SUITE 600
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 6 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Binschus, Chris		chris.binschus@state.co.us	
Heibel, Krystal		krystal.heibel@state.co.us	
,		Regulatory@verdadoil.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
434922	WELL	PR	09/17/2014	OW	123-38370	BRINGELSON RANCH 6-34-9-58	TA
434923	LOCATION	AC			-	BRINGELSON RANCH 6-34-9-58 PAD	AC

General Comment:

This is a Well Pad and Production Facility Field Compliance Audit of the Scout Card, Related Documents and the Location.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type STORAGE OF SUPL

Comment: Tanks still remain on Location; last well appears to have been plugged on 09.13.2024. 3 months to remove all Equipment passed.

Corrective Action: Comply with Rule 1004.a

Date: 09/17/2025

Overall Good:

Spills:

Type	Area	Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 434922 Type: WELL API Number: 123-38370 Status: PR Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: TA - Well appears to have been Plugged and Abandoned per Form 6S (IN PROCESS) 403954455 dated 10.11.2024 with a Surface Plug of 09.03.2024 and Cut and Cap date of 09.13.2024

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 434923 Type: LOCATION API Number: - Status: AC Insp. Status: AC

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI - All wells appear to have been Plugged and Abandoned. Tanks still remain on Location; last well appears to have been plugged on 09.13.2024. 3 months to remove all Equipment passed.

Form 271 - 403814451 dated 06.05.2024 is on File. No Quaterly Form 27S appear to be on File with updates.

Final Reclamation appears to have not begun yet

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
Tanks still remain on Location; last well appears to have been plugged on 09.13.2024. 3 months to remove all Equipment passed.	petrie	09/08/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404345348	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7223219
696307989	Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7223210