

Final Reclamation Inspection

August 25, 2025

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 336691

Inspection Document #: 718800774

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: HSR-KATZEN-63N66W 1SESE

Location ID: 336691



Photo 1. Photo taken from the multi-well location, from HSR-KATZEN #16-1A (API# 123-15101), facing north. Photo illustrates that final reclamation activities have taken place, but vegetation establishment does not meet Rule 1004 standards and bare ground was observed at the well site.



Photo 2. Photo taken from the multi-well location, from HSR-KATZEN #16-1A (API# 123-15101), facing east. See comments under Photo 1.



Inspection Photos

Location Name: HSR-KATZEN-63N66W 1SESE

Location ID: 336691



Photo 3. Photo taken from the multi-well location, from HSR-KATZEN #16-1A (API# 123-15101), facing south. See comments under Photo 1.



Photo 4. Photo taken from the well location, from HSR-KATZEN #16-1A (API# 123-15101), facing west. See comments under Photo 1.



Inspection Photos

Location Name: HSR-KATZEN-63N66W 1SESE

Location ID: 336691



Photo 5. Photo taken of the multi-well location, of HSR-KATZEN #16-1A (API# 123-15101), facing southwest. Photo illustrates that final reclamation activities have taken place, with evidence of drill row seeding, but bare ground remains at the well location.



Photo 6. Photo taken of the access road to the multi-well location, facing east, away from the location. Photo illustrates that final reclamation activities have taken place. However, weedy annual vegetation including puncture vine (*Tribulus terrestris*) was observed across the location.



Inspection Photos

Location Name: HSR-KATZEN-63N66W 1SESE

Location ID: 336691



Photo 7. Photo taken of the access road to the multi-well location, facing west, towards the location. See comments under Photo 6.



Photo 8. Photo taken of ground cover along the access road. Photo illustrates puncture vine (*Tribulus terrestris*), a List C Noxious Weed species.



Inspection Photos

Location Name: HSR-KATZEN-63N66W 1SESE

Location ID: 336691



Photo 9. Photo taken from the multi-well location, from ROCKY MOUNTAIN #37-1 (API# 123-24263), facing north. Photo illustrates that final reclamation activities have taken place, but vegetation establishment does not meet Rule 1004 standards and bare ground was observed at the well site.



Photo 10. Photo taken from the multi-well location, from ROCKY MOUNTAIN #37-1 (API# 123-24263), facing east. See comments under Photo 9.



Inspection Photos

Location Name: HSR-KATZEN-63N66W 1SESE

Location ID: 336691



Photo 11. Photo taken from the multi-well location, from ROCKY MOUNTAIN #37-1 (API# 123-24263), facing south. See comments under Photo 9.



Photo 12. Photo taken from the well location, from ROCKY MOUNTAIN #37-1 (API# 123-24263), facing west. See comments under Photo 9.



Inspection Photos
Location Name: HSR-KATZEN-63N66W 1SESE
Location ID: 336691



Photo 13. Photo taken of the reference area, west of the location, facing west.
Photo illustrates perennial grass vegetation.