

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/15/2025

Submitted Date:

09/15/2025

Document Number:

697011900

FIELD INSPECTION FORM

Loc ID: 302495 Inspector Name: Peterson, Tom On-Site Inspection: 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 69175
Name of Operator: PDC ENERGY INC
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-------|---|---------|
| | | rbucogccinspectionreports@chevron.onmicrosoft.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 299041 | WELL | SI | 06/01/2024 | OW | 123-29235 | GOLD 22-9U | WK |

General Comment:

This is a field audit of the scout card, related documents and the location.

Location

Overall Good:

| | | | |
|----------------------|-----------------|-------|--|
| Signs/Marker: | | | |
| Type | DRILLING/RECOMP | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------------|----------------------|--|-------------|
| Emergency Contact Number: | | | |
| Comment: | <input type="text"/> | | |
| Corrective Action: | <input type="text"/> | | Date: _____ |

Overall Good:

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment:

Multiple Spills and Releases?

| | | | |
|--------------------|----------|-------|--|
| Fencing/: | | | |
| Type | WELLHEAD | | |
| Comment: | Panel | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|---|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Other | # | | |
| Comment: | Rig, pump, work tanks and support equipment are grounded. | | |
| Corrective Action: | | Date: | |
| Type: Flow Line | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Bradenhead | # 1 | | |
| Comment: | Bradenhead valve is exposed at surface. | | |
| Corrective Action: | | Date: | |
| Type: Plunger Lift | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|--|-------|--|
| Venting: | | | |
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|--|-------|--|
| Flaring: | | | |
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Inspected Facilities

Facility ID: 299041 Type: WELL API Number: 123-29235 Status: SI Insp. Status: WK

Cement

Cement Contractor

Contractor Name: Duco

Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____

Circulate to Surface: _____

Cement Fall Back: _____

Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____

Good Return During Job: _____

Production Casing

Cement Volume (sx): _____

Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): 710'-0'

Cement Volume (sx): 59 sxs

Good Return During Job: YES

Cement Type: Class G Neat 15.8#

Comment: Run CBL, RIH with csg punch and perforate csg @ 100' KB 6 SPF, POOH with spent gun, attempts to establish circulation were unsuccessful, RDMO Sure Fire e-line, TIH with tbg to 710' KB, condition wellbore with rig pump, hold safety meeting, MIRU Duco cementers, establish circulation, mix and pump 59 sxs Class G Neat 15.8 ppg cement slurry surface plug (12 bbls total), with cement returned to work tank, RD cementers, lay down tbg, top off cement to surface, RDMO cementers, SIW, RDMO.

Corrective Action: _____

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Seeding | Pass | Seeding | Pass | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 697011901 | Photos | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7238190 |