

# Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON 42A-8D (PARACHUTE CREEK 6 696)

Location #: 335795



Photo # 8499 From entrance to location




Photo # 8500 Location

# Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON 42A-8D (PARACHUTE CREEK 6 696)

Location #: 335795



Photo # 8501 Location



Photo # 8502 Location

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON 42A-8D (PARACHUTE CREEK 6 696)

Location #: 335795



Photo # 8503 Location



Photo # 8504 Mechanical Condition - Possible leak on tubing hanger lock pin

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON 42A-8D (PARACHUTE CREEK 6 696)

Location #: 335795



Photo # 8505 Mechanical Condition - Possible leak on tubing hanger lock pin



Photo # 8506 Mechanical Condition - Possible leak on tubing hanger lock pin

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON 42A-8D (PARACHUTE CREEK 6 696)

Location #: 335795



**Photo # 8507 Mechanical Condition - Possible leak on tubing hanger lock pin**



**Photo # 8508 Mechanical Condition - Possible leak on tubing hanger lock pin**

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON 42A-8D (PARACHUTE CREEK 6 696)

Location #: 335795



**Photo # 8509 Mechanical Condition - Possible leak on tubing hanger lock pin**



**Photo # 8510 Mechanical Condition - Possible leak on tubing hanger lock pin**

## Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON 42A-8D (PARACHUTE CREEK 6 696)

Location #: 335795



Photo # 8511 Mechanical Condition - Possible leak on tubing hanger lock pin



Photo # 8512 Mechanical Condition - Possible leak on tubing hanger lock pin

# Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON 42A-8D (PARACHUTE CREEK 6 696)

Location #: 335795



Photo # 8513 Debris




Photo # 8514 Debris