

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/12/2025

Submitted Date:

09/15/2025

Document Number:

719700098

FIELD INSPECTION FORM

Loc ID: 427337 Inspector Name: Evins, Bret On-Site Inspection: 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 69175
Name of Operator: PDC ENERGY INC
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

19 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		rbucogccinspectionreports@chevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
431426	WELL	PR	11/01/2022	OW	123-36600	Dillard 20Y-401	TA
431427	WELL	SI	04/01/2025	OW	123-36601	Dillard 20T-401	TA
431428	WELL	SI	01/01/2025	OW	123-36602	Dillard 20T-221	TA

General Comment:

*This is an audit of the scout card and related documents followed by a field audit.

Location			
Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action:		Date:	
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Wellsite(s): 3		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	Posted.		
Corrective Action:			Date: _____
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Wellsite(s): 3 Iron panel, braided wire.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Gas Lift injection meter(s), header(s): 1 Iron panel.		
Corrective Action:		Date:	
Equipment:			
Type: Other	# 2		corrective date
Comment:	Wellsite(s): 1 1: Wellhead: w/ Master, casing valves. 1: Gas lift injection line(s).		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Wellsite(s): 1 1: Gas Lift Allocation; (Chevron). Calibration card(s) indicates calibration <= 1 year. Last calibration: 01/16/2025.		
Corrective Action:		Date:	
Type: Pump Jack	# 0		
Comment:	Wellsite(s): 2 Temporarily Abandoned TA. Equipment removed.		

Corrective Action:		Date:	
Type: Bradenhead	# 3		
Comment:	Wellsite(s): 3 Appears plumbed to surface.		
Corrective Action:		Date:	
Type: Other	# 2		
Comment:	Wellsite(s): 2 2: Wellhead: w/ Pumping tee, tubing, casing valves.		
Corrective Action:		Date:	
Type: Prime Mover	# 0		
Comment:	Wellsite(s): 2 Temporarily Abandoned TA. Equipment removed. (Gas engines).		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.552137,-104.564513
Comment:	Centralized Battery serves 1 Location ID (427337). (Well(s): 3: Temporarily Abandoned TA). Centralized Battery serves 1 Tank Battery Facility ID (Pending).				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 431426 Type: WELL API Number: 123-36600 Status: PR Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Temporarily Abandoned | TA.
Disconnected from flowline.
Locked-Out / Tagged-Out | LOTO.
Observed prod. valves shut.

ECMC records last prod: 05/2025.
OOSLAT applied: 06/18/2025.

Corrective Action: Date:

BradenHead

Date of Last Brhd Test: 02/01/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action: Date:

The subreport 'InsnWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 431427 Type: WELL API Number: 123-36601 Status: SI Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Temporarily Abandoned | TA.
Disconnected from flowline.
Locked-Out / Tagged-Out | LOTO.
Observed prod. valves shut.

ECMC records last prod: 05/2025.
OOSLAT applied: 06/18/2025.

Corrective Action: Date:

BradenHead

Date of Last Brhd Test: 02/01/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action: Date:

The subreport 'InsnWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 431428 Type: WELL API Number: 123-36602 Status: SI Insp. Status: TA

Reclamation - Storm Water - Pit						
Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Comment: <input style="width:90%;" type="text"/> Corrective Action: <input style="width:90%;" type="text"/>						Date: _____
Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

ECMC Comments

Comment	User	Date
<p>CECMC Inspection Report Synopsis:</p> <p>On FRI 09/12/2025 at approximately 15:27 hrs. I, Bret Evins, conducted an onsite inspection at: Operator Name: PDC ENERGY INC Location Name: Dillard/20Y-HZ Pad Location ID: 427337 Well Name(s) & API: Reference: See "Inspected Facilities" section on page 1 of this Field Inspection Report. Location County: Weld County, Colorado Weather: Mostly Cloudy, dry.</p> <p>While there, I observed: Well(s): 3: Temporarily Abandoned TA. Battery: Inactive Shut-down.</p> <p>Routine inspection.</p> <p>*Any Corrective Actions from prior inspections that have not been addressed remain applicable.</p>	evinsb	09/15/2025
<p>This is a WELL inspection. Well(s): 3: Temporarily Abandoned TA. Battery: Inactive Shut-down.</p> <p>Centralized Battery serves 1 Location ID (427337). (Well(s): 3: Temporarily Abandoned TA).</p> <p>Centralized Battery serves 1 Tank Battery Facility ID (Pending).</p> <p>Reference (Associated Well(s), Battery Inspections): A.) Field Inspection Report doc. #719700098 and/or Location ID #427337 for TA Well(s) info. B.) Field Inspection Report doc. #719700100 and/or Location ID #427337 for Battery / Facility, Equipment info.</p>	evinsb	09/15/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719700099	Inspection photo(s)	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7238221