

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/04/2025

Submitted Date:

09/10/2025

Document Number:

719500422

**FIELD INSPECTION FORM**

Loc ID 322526 Inspector Name: Morris, Matthew On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10770  
Name of Operator: VISION ENERGY LLC  
Address: P O BOX 370  
City: IGNACIO State: CO Zip: 81137

**Findings:**

- 6 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Energy, Vision		mollieo@maralexinc.com	
Heil, John		john.heil@state.co.us	
Energy, Vision		pbechtolt@maralexinc.com	
Energy, Vision		mrine20@maralexinc.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210720	WELL	PR	08/01/2022	GW	045-06478	FEDERAL-MESAGAR 20-1	PR

**General Comment:**

This is a field audit of the location, scout card, and related documents.

On 9/4/2025 at approximately 11:15, Compliance Inspector Matthew Morris conducted a follow-up audit at VISION ENERGY LLC, FEDERAL-MESAGAR-67S101W/20SENW at Location ID #322526 in Garfield County, Colorado.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	(970)563-0082	Date:	
Corrective Action:			

Overall Good:

**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	PIT		
Comment:	Livestock fencing		
Corrective Action:		Date:	

**Equipment:**

Type	Area	Volume	corrective date
Type: Bradenhead		# 1	
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run		# 1	
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator		# 1	
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift		# 1	
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors		# 2	
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 210720 Type: WELL API Number: 045-06478 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
		Culverts				
		Gravel				
Compaction						
Gravel						
		Compaction				

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

Type: \_\_\_\_\_ Lined: NO Pit ID: \_\_\_\_\_ Lat: \_\_\_\_\_ Long: \_\_\_\_\_

Reference Point: \_\_\_\_\_ Other: \_\_\_\_\_ Length: \_\_\_\_\_ Width: \_\_\_\_\_

**Lining:**

Liner Type: \_\_\_\_\_ Liner Condition: \_\_\_\_\_

Comment:

Pit on location has no permit on file.

Date: 09/25/2025

Corrective Action

Operators will ensure that the Pits they operate are:  
 (1) Properly permitted through a Form 15 approved by the Director, or registered in their names with an active Pit Facility ID;  
 (2) Accurately mapped; and  
 (3) Listed according to current facility records in the Commission's database. Operators may update facility records using a Form 15.

**Fencing:**

Fencing Type: Livestock Fencing Condition: Adequate

Comment:

Corrective Action

Date: \_\_\_\_\_

**Netting:**

Netting Type: Metal Grid Netting Condition: Good

Comment:

Fluid level in pit is higher than netting and poses a wildlife hazard.

Date: 09/10/2025

Corrective Action

Net pit to prevent wildlife access.

Anchor Trench Present: \_\_\_\_\_ Oil Accumulation: \_\_\_\_\_ 2+ feet Freeboard: \_\_\_\_\_

Comment:

Corrective Action

Date: \_\_\_\_\_

**ECMC Comments**

Comment	User	Date
<p>During the audit, the following compliance issues were observed:</p> <p>1) Insufficient netting over production pit/wildlife hazard 2) Production pit has no permit on file</p> <p>A follow-up on this site audit will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.</p>	morrisism	09/10/2025

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404349222	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7226809">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7226809</a>
719500425	Photo Log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7226802">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7226802</a>