

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/16/2025

Submitted Date:

09/17/2025

Document Number:

716900175

FIELD INSPECTION FORM

Loc ID 320276 Inspector Name: Huck, Keith On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1700 LINCOLN ST STE 4550
City: DENVER State: CO Zip: 80203

Findings:

- 7 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203332	WELL	SI	05/01/2021	OW	001-08841	JOHN WEIGANDT B 1	SI

General Comment:

[Follow Up Inspection from Document#717000448 and Document#715801429. Corrective Action for Weeds has not been addressed from these two inspections](#)

Location

Overall Good:

Signs/Marker:

	Type WELLHEAD		
	Comment: Adequate		
	Corrective Action:		Date:

Emergency Contact Number:

Comment: Adequate			Date: _____
Corrective Action:			

Good Housekeeping:

Type	WEEDS		
	Comment: Weeds still not addressed from last two inspections. Please cut and remove thick and tall vegetation		
	Corrective Action: Comply with Rule 606		Date: 09/26/2025

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No	NO		
	Comment:		
	Corrective Action:		Date:

Flaring:

Type			
	Comment:		
	Corrective Action:		Date:

Inspected Facilities

Facility ID: 203332 Type: WELL API Number: 001-08841 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary On Tuesday 9-16-2025 at approximately 10:14am. I, Inspector Chane Finkenbinder, Conducted an audit of the well scout card & related forms followed by an onsite inspection: Operator: KP Kauffman Location # 320276 API # 05-001-08841 Well name: John Weigant B1 County: Adams Weather: Cloudy Temp: 76* Location: Dry While there, I observed a wellsite, SI at the time of inspection. During this inspection the following possible compliance issues were observed: 606 Housekeeping: Vegetation needs to be cut & removed, CA date 9-26-2025. Any corrective actions from previous Inspections that have not been addressed are still applicable. See attached photos. A follow up on this site inspection will be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules.</p>	huckk	09/17/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
716900176	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7240496