

# Inspection Photos

**09/10/2025**

**Operator:** PETROLEUM RESOURCE MANAGEMENT  
CORP - #10421

**Location ID:** 485573

**Inspection Document #:** 718600968

Moffat County, CO

Logan Maxwell  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Location Name: Duncan Unpermitted Facility

Location ID: 485573




**Photo 1.** Photo taken from the east side of the stream crossing, facing southwest. Photo illustrates that construction of the stream crossing is still occurring at the Location.



**Photo 2.** Photo taken from the southwestern portion of the location, facing west. Photo illustrates that the surplus material/debris was removed.

Inspection Photos  
Location Name: Duncan Unpermitted Facility  
Location ID: 485573



**Photo 3.** Photo taken of the cut slope of the northern portion of the Location, facing northeast. Photo illustrates an example that undesirable weed species are still present on the Location (see also red arrows for the presence of weeds).



Inspection  
Location Name: Dunca  
Location I



**Photo 4.** Photo taken of the cut slope on the northern portion of the Location, illustrating that some areas remain bare without vegetation.



**Photo 5.** Photos 5-7 taken on top of the fill slope, on the eastern portion of the location, illustrating cracking along the fill slopes that are recurring.



**Photo 6.** See comments under Photo 6.



**Photo 7.** See comments under Photo 6.