

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/08/2025

Submitted Date:

09/11/2025

Document Number:

719500430

FIELD INSPECTION FORM

Loc ID 322495 Inspector Name: Morris, Matthew On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10770
Name of Operator: VISION ENERGY LLC
Address: P O BOX 370
City: IGNACIO State: CO Zip: 81137

Findings:

- 12 Number of Comments
- 6 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Energy, Vision		mollieo@maralexinc.com	
Energy, Vision		pbechtolt@maralexinc.com	
Energy, Vision		mrine20@maralexinc.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210630	WELL	TA	07/01/2021	GW	045-06386	CALF CANYON-FEDERAL 26-1	TA

General Comment:

This is a field audit of the location, scout card, and related documents.

On 9/8/2025 at approximately 13:30, Compliance Inspector Matthew Morris conducted a follow-up audit at VISION ENERGY LLC, CALF CANYON-FEDERAL-66S102W/26NWNW at Location ID #322495 in Garfield County, Colorado.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

Location

Overall Good:

Signs/Marker:

Type	BATTERY		
Comment:	Battery sign contains inaccurate information.		
Corrective Action:	Install sign to comply with CECMC rules.	Date:	10/12/2025
Type	TANK LABELS/PLACARDS		
Comment:	No labels posted on storage tank.		
Corrective Action:	Install labels to comply with CECMC rules.	Date:	10/11/2024
Type	WELLHEAD		
Comment:	No wellhead sign.		
Corrective Action:	Install sign to comply with CECMC rules.	Date:	10/11/2024

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	Weeds present across location.		
Corrective Action:	Remove weeds from location.	Date:	09/19/2025

Overall Good:

Spills:

Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	TANK BATTERY		
Comment:	Livestock fencing		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Livestock fencing		
Corrective Action:		Date:	

Equipment:

Type			corrective date
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	

Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth		Walls Insufficient	Base Insufficient	Inadequate
Comment:	Weeds/vegetation have compromised berm integrity.			
Corrective Action:	Maintain/repair to ensure containment structure is sufficiently impervious to contain spilled or released materials.			Date: 10/12/2025

Venting:

Yes/No	NO	
Comment:		
Corrective Action:	Date:	

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 210630 Type: WELL API Number: 045-06386 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Defined Inactive 7/2021. MIT to maintain status is due by 12/2025.

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 03/26/2024 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 250 Fluid Type: GAS

End Surf Csg Pressure: 25

Comment: Bradenhead is past due for annual testing. 10/12/2025

Corrective Action: For all Wells other than coalbed methane Wells, an Operator will perform an annual Bradenhead test and submit the data to the Director on a Form 17 or other Director-approved method. Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction				
		Gravel				
Compaction						
		Culverts				
Berms						
		Ditches				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>During the audit, the following compliance issues were observed:</p> <ul style="list-style-type: none"> 1) Inaccurate information on battery sign 2) No wellhead sign posted 3) No labels posted on storage tank 4) Weeds across location 5) Containment berm permeability compromised due to weed/vegetation growth 6) Annual Bradenhead test has not been performed <p>A follow-up on this site audit will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.</p>	morris	09/11/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404351026	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7228695
719500431	Photo Log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7228683