

Inspection Photos
Location Name: Raisley 21-34
Location ID: 329009



Photo 1: erosion

Photo 2: Erosion

Inspection Photos
Location Name: Raisley 21-34
Location ID: 329009



Photo 3: location from entrance

Photo 4: Wellhead sign not legible, damage

Inspection Photos
Location Name: Raisley 21-34
Location ID: 329009



Photo 5: TA Wellhead



Photo 6: Equipment

Inspection Photos
Location Name: Raisley 21-34
Location ID: 329009



Sep 17, 2025 at 2:02:02 PM
286° W
Weld County
ECMC



Sep 17, 2025 at 2:02:12 PM
295° NW
Weld County
ECMC

Photo 7: Operator name not displayed, damaged tank battery sign

Photo 8: tank battery