

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/17/2025

Submitted Date:

09/17/2025

Document Number:

714202512

FIELD INSPECTION FORM

Loc ID 332631 Inspector Name: Santistevan, Brittani On-Site Inspection 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 69175
Name of Operator: PDC ENERGY INC
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 12 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
White, Jeffery		jeffery.white@chevron.com	All Inspections
,		cogccinspection@pdce.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
245364	WELL	PR	11/01/2017	GW	123-13159	HARD-FOUGHT 1-35	PR
270294	WELL	PR	04/01/2025	OW	123-21859	RODRIGUEZ 4-35	PR

General Comment:

[This is an audit of HARD FOUGHT 1-35, RODRIGUEZ 4-35 scout card and related documents followed by a field inspection.](#)

Location

Overall Good:

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	ADEQUATE		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	ADEQUATE		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	ADEQUATE		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	PANEL		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 2		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 2		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		

Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 2		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	OTHER	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	315 BBLs	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLs	PBV FIBERGLASS		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shares containment with other tanks.			
Corrective Action:				

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		

Flaring:

Type	
------	--

Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 245364 Type: WELL API Number: 123-13159 Status: PR Insp. Status: PR

Producing Well

Comment: PR; valves appear to be in the open position.

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 07/07/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 270294 Type: WELL API Number: 123-21859 Status: PR Insp. Status: PR

Producing Well

Comment: PR; valves appear to be in the open position.

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 07/07/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Fail	Gravel	Pass			

Comment: [it appears to be erosion on multiple areas of location. See attached photos.](#)

Corrective Action: [Install proper BMP's per Rule 1002.f.\(2\).C.](#)

Date: 10/31/2025

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>ECMC Audit Report Summary WEATHER CONDITIONS: sunny, wet ground. On Wednesday, September 17, 2025 at approximately 1100, I, Inspector Brittani Santistevan, conducted an on-site inspection at HAR FOUGHT 1-35, RODRIGUEZ 4-35 (PDC Energy), at location ID: 332631 in WELD COUNTY, Colorado. While there, I observed a producing facility. During this inspection the following possible compliance issues were observed: 1. It appears to be erosion on multiple areas of the location. Install proper BMPs per Rule 1002.f.(2).C. (Corrective Action Date: October 31, 2025) See attached photo #4, 5, 10, 11, 13-15.</p> <p>A follow up on this site audit needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules. This is a summary of the audit report.</p>	santistb	09/17/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
714202513	Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7242232