

Inspection Photos

09/08/2025

Operator: TEP Rocky Mountain LLC #96850

Location ID: 335543

Inspection Doc: 719200181

Garfield County, CO

Emily Gaasche
NW Reclamation Specialist
ECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335543



Photo 1: Photos showing an overview of the location looking north and south, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335543



Photo 2: Photos showing an overview of the location looking east and west, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335543



Photo 3: Kochia, cheatgrass, and rubber rabbitbrush is present around the wellheads and on the working pad surface. See previous inspections for Corrective Action. This Corrective Action remains outstanding.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335543



Photo 4: Photo showing the eastern interim area above the cut slope. These areas appear to be dominated by annual pepperweeds and annual false wheatgrass and are not progressing towards 1003 reclamation requirements.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335543



Photo 5: Photos showing the western interim areas are composed of Russian wildrye, intermediate wheatgrass and secondary amounts of rubber rabbitbrush. These portions of the interim areas are progressing towards 1003 reclamation requirements.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335543



Photo 6: Photo showing the eastern and northeastern cut slopes behind production equipment, respectively. The cut slopes appear to be predominantly bare with rilling and sediment deposition occurring. Implement or maintain stormwater BMP's.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335543



Photo 7: A culvert along the access road appears to have accumulated a build-up of vegetative debris and sediment. Maintain stormwater BMP's.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources