

# Inspection Photos

09/08/2025

**Operator:** TEP Rocky Mountain LLC #96850

**Location ID:** 335271

**Inspection Doc:** 719200201

Garfield County, CO

Emily Gaasche  
NW Reclamation Specialist  
ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335271



**Photo 1:** Photos show an overview of the location looking north and south, respectively.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335271



**Photo 2:** Photos show an overview of the location looking east and west, respectively.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335271



**Photo 3:** Photos showing stormwater controls on the northeastern and southern portions of the location, respectively. Stormwater BMP's are in disrepair. Comply with Rule 1002.f.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335271



**Photo 4:** Photos showing stormwater controls on the northern portion of the location. Stormwater BMP's are in disrepair or in need of maintenance. Comply with Rule 1002.f.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335271



**Photo 5:** Photos showing fencing around the wellheads is in disrepair and insufficient to prevent livestock or wildlife entry. Maintenance is advised.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335271



**Photo 6:** Photos showing the southwestern cut slope. Desirable vegetation has established on portions of the cut slope.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335271



**Photo 7:** Photo showing the northwestern interim area is composed of mostly bare ground. Reseeding and reclamation efforts are not apparent. Comply with 1003 reclamation rules.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335271



**Photo 8:** Photos showing some culverts at the location appear to have an accumulation of sediment deposition, reducing capacity. Maintenance is required.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources