

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/08/2025

Submitted Date:

09/12/2025

Document Number:

719500432

FIELD INSPECTION FORM

Loc ID 312579 Inspector Name: Morris, Matthew On-Site Inspection 2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:
 ECMC Operator Number: 10770
 Name of Operator: VISION ENERGY LLC
 Address: P O BOX 370
 City: IGNACIO State: CO Zip: 81137

Findings:
11 Number of Comments
6 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Energy, Vision		mollieo@maralexinc.com	
Energy, Vision		mrine20@maralexinc.com	
Energy, Vision		pbechtolt@maralexinc.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221955	WELL	SI	03/01/1990	GW	077-08557	CAMP GULCH UNIT-FEDERAL 1-24-8-103	TA

General Comment:

This is a field audit of the location, scout card, and related documents.

On 9/8/2025 at approximately 14:00, Compliance Inspector Matthew Morris conducted a follow-up audit at VISION ENERGY LLC, CAMP GULCH UNIT-FEDERAL-68S103W/24SESE at Location ID #312579 in Garfield County, Colorado.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	No battery sign posted.		
Corrective Action:	Install sign to comply with CECMC rules.	Date:	10/13/2025
Type	TANK LABELS/PLACARDS		
Comment:	No tank labels posted on storage tank.		
Corrective Action:	Install labels on storage tank to comply with CECMC rules.	Date:	10/13/2025

Emergency Contact Number:

Comment: 911/(970)563-0082

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Unused storage tank on location and not within secondary containment.		
Corrective Action:	Remove unused equipment from location.	Date:	10/13/2025
Type	WEEDS		
Comment:	Weeds on location.		
Corrective Action:	Remove weeds from location.	Date:	09/20/2025

Overall Good:

Spills:

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type	#	Capacity	Type	Tank ID	SE GPS	corrective date
Gas Meter Run	# 1					
Comment:						
Corrective Action:						Date:
Bradenhead	# 1					
Comment:						
Corrective Action:						Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER	1		STEEL AST		,
Comment:	Wildlife entry hazard on storage tank.				

Corrective Action: Secure equipment to prevent wildlife entry.	Date: <u>09/18/2025</u>
---	-------------------------

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment: Tank does not have secondary containment installed.				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:	Date:	

Inspected Facilities

Facility ID: 221955 Type: WELL API Number: 077-08557 Status: SI Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Well is TA. MIT is due November 2025 to maintain TA status.

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 03/25/2024 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: Annual Bradenhead test has not been performed.

10/13/2025

Corrective Action: For all Wells other than coalbed methane Wells, an Operator will perform an annual Bradenhead test and submit the data to the Director on a Form 17 or other Director-approved method.

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction						
		Gravel				
		Culverts				
		Compaction				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>During the audit, the following compliance issues were observed:</p> <ul style="list-style-type: none"> 1) No battery sign posted 2) No tank labels posted on storage tank 3) Weeds on location 4) Unused equipment 5) Wildlife entry hazard on storage tank 6) Annual Bradenhead testing has not been performed <p>A follow-up on this site audit will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.</p>	morris	09/12/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404352914	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7230950
719500433	Photo Log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7230948