

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/17/2025

Submitted Date:

09/19/2025

Document Number:

713401086

**FIELD INSPECTION FORM**

Loc ID 314651 Inspector Name: Popejoy, Dusty On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10539  
Name of Operator: UTAH GAS OP LTD DBA UTAH GAS CORP  
Address: 734 MAIN STREET 3RD FLOOR  
City: GRAND JUNCTION State: CO Zip: 81501

**Findings:**

- 14 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
GAS, UTAH		inspections@utahgascorp.com	
Koch, Benjamin		bzkoch@blm.gov	
Kellerby, Shaun		shaun.kellerby@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
229197	WELL	PR	06/25/1961	GW	103-06284	DOUGLAS CREEK UNIT 7	PR

**General Comment:**

[This is a Field Inspection/audit of the scout card, related documents and the location.](#)

Location			
<b>Lease Road:</b>			
Type	Access		
comment:	Access		
Corrective ActionL		Date:	
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:	Battery sign contains inaccurate nearest public road information Sign on meter house		
Corrective Action:	Comply with CECMC Signage rules	Date:	09/05/2025
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
<b>Emergency Contact Number:</b>			
Comment:	970-693-6021/911		
Corrective Action:			Date: _____
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No _____			
Comment: _____			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Equipment:</b>			
Type: Plunger Lift	# 1		corrective date
Comment:	Well on plunger lift		
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Flameless gas infrared catalytic heater		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	No form of pressure monitoring equipment. Bradenhead valve is accessible		
Corrective Action:		Date:	

Type: Deadman # & Marked	# 4	
Comment:		
Corrective Action:		Date:
Type: Gas Meter Run	# 1	
Comment:		
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLs	Open Top		
Comment:	Tank not equipped with telemetry				
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	30 bbls
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent		
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO
Comment:	
Corrective Action:	Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 229197 Type: WELL API Number: 103-06284 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing well on plunger lift](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches						
Compaction						Light compaction
		Compaction				Light compaction
Berms						
		Ditches				
Other	Fail					Failure to minimize erosion & sediment
		Berms				

Comment: 1. Failure to minimize erosion & transport of sediment - Erosion & transport of sediment on outslope/sediment migrating onto location/insufficient BMP's

Corrective Action: **Comply with CECMC Stormwater rules** Date: 08/20/2025

**Pits:**  NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<p><a href="#">CECMC Inspection/Audit Report Summary</a></p> <p>On 09/17/2025 at approximately 12:48 hours, Compliance Inspector Dusty Popejoy conducted a follow up inspection/audit at UTAH GAS OP LTD DBA UTAH GAS CORP DOUGLAS CREEK UNIT #7 PAD at Location ID #314651 in Rio Blanco County, Colorado.</p> <p>Please refer to inspection/audit 713400953 conducted on 07/29/2025, 2 of 4 corrective actions have been completed. Failure to minimize erosion &amp; transport of sediment/insufficient BMP's &amp; Battery sign contains inaccurate nearest public road information are not resolved and corrective action dates remain the same.</p> <p>This location is within or in close proximity to a Parks and Wildlife (CPW) District with High Priority, NSO, Density Habitat regulations.</p> <p>While there, I observed normal production operations.</p> <p>During the inspection/audit, the following compliance issues were observed:</p> <ol style="list-style-type: none"> <li>Stormwater - Failure to minimize erosion &amp; transport of sediment/insufficient BMP's with a CA date of 08/20/2025</li> <li>Signs/Marker - Battery sign contains inaccurate nearest public road information with a CA date of 09/5/2025</li> </ol> <p>A follow-up on this site inspection/audit will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.</p> <p>This is a summary of inspection/audit report.</p>	popejoyd	09/19/2025

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713401087	713401086 Inspection-Audit Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7245137">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7245137</a>