

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DOUGLAS CREEK UNIT #50 PAD

Location ID: 311826

Date: 09/17/2025



Photo # 3562 Entrance to location



Photo # 3570 Location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DOUGLAS CREEK UNIT #50 PAD

Location ID: 311826

Date: 09/17/2025



Photo # 3563 Location



Photo # 3567 Location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DOUGLAS CREEK UNIT #50 PAD

Location ID: 311826

Date: 09/17/2025



Photo # 3580 SE corner of location



Photo # 3581 SW corner of location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DOUGLAS CREEK UNIT #50 PAD

Location ID: 311826

Date: 09/17/2025



Photo # 3582 NW corner of location



Photo # 3583 NE corner of location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DOUGLAS CREEK UNIT #50 PAD

Location ID: 311826

Date: 09/17/2025



Photo # 3575 Unused flowline lacks lockout tagout (OOSLAT) & has open ended piping/wildlife hazard/available for entry by wildlife



Photo # 3577 Unused flowline lacks lockout tagout (OOSLAT)

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DOUGLAS CREEK UNIT #50 PAD

Location ID: 311826

Date: 09/17/2025



Photo # 3578 Open ended piping/wildlife hazard/available for entry by wildlife



Photo # 3565 Wellhead sign lacks required information/not in compliance with CECMC rules

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DOUGLAS CREEK UNIT #50 PAD

Location ID: 311826

Date: 09/17/2025



Photo # 3584 Debris



Photo # 3585 Debris

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DOUGLAS CREEK UNIT #50 PAD

Location ID: 311826

Date: 09/17/2025



Photo # 3587 Debris



Photo # 3594 Debris