

# Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC AP 41-11-696

Location ID: 335874



Photo # 1185 From entrance to location



Photo # 1186 Location

# Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC AP 41-11-696

Location ID: 335874



Photo # 1187 Location




Photo # 1188 Location

# Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC AP 41-11-696

Location ID: 335874




Photo # 1189 Location

Photo # 1190 Location

# Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC AP 41-11-696

Location ID: 335874




Photo # 1191 Location



Photo # 1192 Open ended load line

# Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC AP 41-11-696

Location ID: 335874



Photo # 1193 Open ended load line



Photo # 1194 Open ended load line

# Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC AP 41-11-696

Location ID: 335874



Photo # 1195 Open ended load line



Photo # 1196 Open ended load line

# Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC AP 41-11-696

Location ID: 335874



Photo # 1197 Open ended load line



Photo # 1198 Open ended load line

# Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC AP 41-11-696

Location ID: 335874



Photo # 1199 Open ended load line



Photo # 1200 Open ended piping on separator/wildlife hazards/available for entry by wildlife

# Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC AP 41-11-696

Location ID: 335874



**Photo # 1201 Open ended piping on separator/wildlife hazard/available for entry by wildlife**



**Photo # 1202 Open ended piping on separator/wildlife hazard/available for entry by wildlife**

# Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC AP 41-11-696

Location ID: 335874




Photo # 1203 Unmarked deadman



Photo # 1204 Same unmarked deadman

# Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC AP 41-11-696

Location ID: 335874




Photo # 1205 Unmarked deadman



Photo # 1206 Same unmarked deadman

# Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC AP 41-11-696

Location ID: 335874



Photo # 1207 Debris

Photo # 1208 Debris

# Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC AP 41-11-696

Location ID: 335874



Photo # 1209 PRV vent line on tank burner does not comply with CECMC pressure safety device rules



Photo # 1210 PRV vent line on tank burner does not comply with CECMC pressure safety device rules

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC AP 41-11-696

Location ID: 335874



Photo # 1211 PRV vent line on tank burner does not comply with CECMC pressure safety device rules




Photo # 1212 Labeling on methanol tank weathered & damaged/starting to become illegible

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC AP 41-11-696

Location ID: 335874



Photo # 1213 Battery sign weathered & faded/starting to become illegible



Photo # 1214 Tank battery containment showing some signs of damage

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC AP 41-11-696

Location ID: 335874



Photo # 1215 Tank battery containment showing some signs of damage