

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/20/2025

Submitted Date:

09/21/2025

Document Number:

708907495

FIELD INSPECTION FORM

Loc ID 335094 Inspector Name: Smelser, Wayne On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

Findings:

29 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Koch, Benjamin		bzkoch@blm.gov	
TEP		ECMCInspectionReports@flywheelenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
262908	WELL	PR	01/13/2003	GW	045-08073	FEDERAL PA 23-27	PR
262910	WELL	PR	01/06/2003	GW	045-08075	FEDERAL PA 323-27	PR
272791	WELL	PR	02/12/2005	GW	045-10155	FEDERAL PA 513-27	PR
272792	WELL	PR	08/29/2005	GW	045-10154	FEDERAL PA 413-27	PR
285491	WELL	PR	06/30/2006	GW	045-12509	FEDERAL PA 523-27	PR
285493	WELL	PR	06/30/2006	GW	045-12508	FEDERAL PA 423-27	PR

General Comment:

[This is a Field Inspection/Audit of the scout card, related documents and the location.](#)

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	911/970-285-9377		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	DEBRIS		
Comment:	Debris - please refer to photo log		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No _____			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	OTHER		
Comment:	Air compressor - hog panels		
Corrective Action:			Date:
Type	TANK BATTERY		
Comment:	Hog panels		

Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bradenhead	# 6		
Comment:	FEDERAL PA23-27, FEDERAL PA413-27 & FEDERAL PA523-27 wells have Taylor plugs located on bradenheads, bradenhead valves are accessible FEDERAL PA323-27 & FEDERAL PA423-27 wells have pressure transducers & Taylor plugs located on bradenheads, bradenhead valves are accessible FEDERAL PA513-27 well has no form of pressure monitoring equipment located on bradenhead, bradenhead valve is accessible		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 2		
Comment:	Marked		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Air compressor		
Corrective Action:		Date:	
Type: Plunger Lift	# 6		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	
Type: Gas Meter Run	# 6		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 6		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	STEEL AST		,
Comment:	Tank equipped with telemetry				
Corrective Action:					Date:

Paint

Condition	Adequate
-----------	----------

Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent		

Comment:	Centralized containment
Corrective Action:	Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLs	STEEL AST		

Comment:	Tank equipped with telemetry
Corrective Action:	Date:

Paint

Condition	Adequate
-----------	----------

Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent		

Comment:	Centralized containment
Corrective Action:	Date:

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities										
Facility ID:	262908	Type:	WELL	API Number:	045-08073	Status:	PR	Insp. Status:	PR	
Producing Well										
Comment:	Producing, well on plunger lift								Date:	
Corrective Action:									Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12										
Facility ID:	262910	Type:	WELL	API Number:	045-08075	Status:	PR	Insp. Status:	PR	
Producing Well										
Comment:	Producing, well on plunger lift								Date:	
Corrective Action:									Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12										
Facility ID:	272791	Type:	WELL	API Number:	045-10155	Status:	PR	Insp. Status:	PR	
Producing Well										
Comment:	Producing, well on plunger lift								Date:	
Corrective Action:									Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12										
Facility ID:	272792	Type:	WELL	API Number:	045-10154	Status:	PR	Insp. Status:	PR	
Producing Well										
Comment:	Producing, well on plunger lift								Date:	
Corrective Action:									Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12										
Facility ID:	285491	Type:	WELL	API Number:	045-12509	Status:	PR	Insp. Status:	PR	
Producing Well										
Comment:	Producing, well on plunger lift								Date:	
Corrective Action:									Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12										
Facility ID:	285493	Type:	WELL	API Number:	045-12508	Status:	PR	Insp. Status:	PR	
Producing Well										
Comment:	Producing, well on plunger lift								Date:	
Corrective Action:									Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12										

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts				
		Ditches				
Gravel						Sparse to none in some areas
Berms						
Compaction						Light compaction in some areas
		Berms				
Culverts						
		Gravel				Sparse to none in sections
Sediment Traps						
Ditches						
Rip Rap						
		Tracking Pad				Aggregate/gravel based VTC & FODS trackout mats
		Compaction				Light compaction in some sections
		Check Dams				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>CECMC Inspection/Audit Report Summary On 09/20/2025 at approximately 11:03 hours, I, Compliance Specialist, Wayne Smelser Conducted a follow up inspection/audit at TEP ROCKY MOUNTAIN LLC FEDERAL PA23-27 Pad. Location # 335094 in Garfield County Colorado. Please refer to inspection/audit 719500150 conducted on 06/27/2025, previous corrective action has been completed. Location is within High Priority/Density Habitat areas. Location is within Rule 411a Surface Water External Buffer. While there, I observed normal production operations.</p> <p>Comments -</p> <p>Housekeeping - Debris</p> <p>This is a summary of inspection/audit report.</p>	smelserw	09/21/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708907496	Inspection/Audit 708907495 Stormwater photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7246059
708907497	Inspection/Audit 708907495 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7246060