

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/08/2025

Submitted Date:

09/08/2025

Document Number:

714202494

FIELD INSPECTION FORM

Loc ID 332774 Inspector Name: Santistevan, Brittani On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 69175
Name of Operator: PDC ENERGY INC
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

Findings:

- 16 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		cogccinspection@pdce.com	All Inspections
White, Jeffery		jeffery.white@chevron.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
293137	WELL	PR	12/01/2023	GW	123-26483	SCHANK J 36-31	PR
294029	WELL	PR	12/01/2023	GW	123-26672	SCHANK J 35-27	SI

General Comment:

[This is an audit of SCHANK J 36-31, 35-27 scout card and related documents followed by a field inspection.](#)

Location

Overall Good:

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	ADEQUATE		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	ADEQUATE		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	ADEQUATE		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			Date: _____
Corrective Action:			

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment: _____

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	6' CHAIN LINK		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	6' CHAIN LINK		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	6' CHAIN LINK		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Plunger Lift	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 2		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		

Comment:		Date:	
Corrective Action:		Date:	
Type: Emission Control Device	# 2		
Comment:		Date:	
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:	IT APPEARS THE SEPARATORS ARE NOT ANCHORED. SEE ATTACHED PHOTOS.	Date:	
Corrective Action:	COMPLY WITH RULE 607.	Date:	10/08/2025
Type: Bird Protectors	# 4		
Comment:		Date:	
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	3	OTHER	BV CONCRETE		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	60 BBLs
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	SHARES CONTAINMENT WITH OTHER TANKS.			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	3	300 BBLs	STEEL AST		
Comment:	ACCORDING TO ECMC MAPS, LOCATION IS WITHIN FLOOD PLAINS. IT APPEARS TANKS ARE ANCHORED.				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				

Corrective Action:		Date:	
--------------------	--	-------	--

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 293137 Type: WELL API Number: 123-26483 Status: PR Insp. Status: PR

Producing Well

Comment: PR; VALVES APPEAR TO BE IN THE OPEN POSITION

Corrective Action: _____

Date: _____

BradenHead

Date of Last Brhd Test: 08/29/2024 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 2 Fluid Type: WATER AND GAS

End Surf Csg Pressure: 0

Comment: SUBMIT REPORT

Corrective Action: _____

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 294029 Type: WELL API Number: 123-26672 Status: PR Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment: SI; VALVES APPEAR TO BE IN THE CLOSED POSTION.

Corrective Action: _____

Date: _____

BradenHead

Date of Last Brhd Test: 08/20/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 15 Fluid Type: WATER H2O

End Surf Csg Pressure: 1

Comment: _____

Corrective Action: _____

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>ECMC Audit Report Summary WEATHER CONDITIONS: sunny, dry ground. On Monday, September 8, 2025 at approximately 1200, I, Inspector Brittani Santistevan, conducted an on-site inspection at SCHANK J 36-31, 35-27 (PDC Energy), at location ID: 332774 in WELD COUNTY, Colorado. While there, I observed a producing facility. During this inspection the following possible compliance issues were observed: 1. It appears the separators are not anchored. According to ECMC maps, the location is within the floodplains. Anchor equipment ensuring anchors are engineered to ensure the equipment will resist flotation, collapse, lateral movement, or subsidence per Rule 607. (Corrective Action Date: October 8, 2025) See attached photo # 9-12.</p> <p>A follow up on this site audit needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules. This is a summary of the audit report.</p>	santistb	09/08/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404353834	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7236920
714202495	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7236907