

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/11/2025

Submitted Date:

09/15/2025

Document Number:

708700132

FIELD INSPECTION FORM

Loc ID: 333566 Inspector Name: Kosola, Jason On-Site Inspection: 2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:
 4 Number of Comments
 1 Number of Corrective Actions
 Corrective Action Response Requested

Operator Information:
 ECMC Operator Number: 53255
 Name of Operator: MARALEX RESOURCES INC
 Address: P O BOX 338
 City: IGNACIO State: CO Zip: 81137

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
,		pbechtolt@maralexinc.com	
Fischer, Alex		alex.fischer@state.co.us	
Schroeder, Siera		siera.schroeder@state.co.us	
,		mollieo@maralexinc.com	All Inspections
McDonough, Corey		corey.mcdonough@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214932	WELL	PA	01/03/2022	GW	067-06537	SHELHAMMER 1	EI

General Comment:

This is an environmental inspection to document status of Remediation 21214 which was submitted for plugging and abandonment of well. Remediation 21214 is in violation of rule 913.e.(3) Reporting Schedule. No Form 27 has been submitted since 4th quarter of 2024. No analytical results from the wellhead area have been submitted to ECMC.

Corrective actions from previous inspections have not been addressed. Inspection 700300752 conducted on 10/01/2024 noted oily impacts around partially buried vessel and required compliance with Rule 12 and 913.c with a Corrective Action date of 10/04/2024. Follow up inspection 708700063 conducted on 11/12/2024 found the same oily impacts still present. This inspection conducted on 9/11/2025 also found the same oily impacts in place.

All other Corrective Actions from previous inspections remain in effect.

Operator has not complied with Conditions of Approval on Form 27 Initial 402895884.

Operator has failed Final Reclamation on previous inspection reports.

Operator is subject to Notice of Alleged Violation for multiple violations on this location and should take immediate steps to remedy correction actions to avoid issuance of a Notice of Alleged Violation.

Inspected Facilities

Facility ID: 214932 Type: WELL API Number: 067-06537 Status: PA Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Environmental

Spill/Remediation:

Comment: [Operator has not updated Remediation 21214 since 4th quarter 2024. Operator has not submitted required soil sampling around wellhead per Remediation 21214](#)

Corrective Action: [Submit Form 27 with soil sample plan per Rule 913.](#)

Date: 09/30/2025

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

ECMC Comments

Comment	User	Date
Location has remained in the same condition since October 2024.	Kosolaj	09/15/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404354150	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7237182
708700133	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7237181