

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
09/17/2025
Submitted Date:
09/19/2025
Document Number:
717300484

FIELD INSPECTION FORM

Loc ID 318531 Inspector Name: Maclaren, Joe On-Site Inspection 2A Doc Num: _____

Status Summary:

THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Operator Information:

ECMC Operator Number: 46290
 Name of Operator: KP KAUFFMAN COMPANY INC
 Address: 1700 LINCOLN ST STE 4550
 City: DENVER State: CO Zip: 80203

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Case, Dustin		dcase@kpk.com	
McCoy, Diane		diane.mccoy@state.co.us	
Watzman, Ross		rwatzman@kpk.com	
Silver, Randy		randy.silver@state.co.us	
		cogcc@kpk.com	
Burn, Diana		diana.burn@state.co.us	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Clark, Lily		lclark@kpk.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241514	WELL	SI	05/01/2024	OW	123-09303	COSSLETT 2	PA

General Comment:

ECMC Engineering Integrity Inspection
 ECMC Integrity Inspector on site 9/17 & 9/19/2025
 FLIR & RMLD Surveys Performed
 Well has been plugged and abandoned
 Photo Log Uploaded

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type	Flow Line	#		corrective date
	Comment: No flowlines/ flowline risers observed at PA well area.			
	Corrective Action: <input type="text"/>			Date: <input type="text"/>

Venting:

Yes/No	<input type="text"/>		
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: <input type="text"/>

Flaring:

Type	<input type="text"/>		
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: <input type="text"/>

Inspected Facilities

Facility ID: 241514 Type: WELL API Number: 123-09303 Status: SI Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

