

# Inspection Photos

09/12/2025

**Operator:** TEP Rocky Mountain LLC #96850

**Location ID:** 335543

**Inspection Doc:** 719200220

Garfield County, CO

Emily Gaasche  
NW Reclamation Specialist  
ECMC



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335543



**Photo 1:** Photos show an overview of the location looking north and south, respectively.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335543



**Photo 2:** Photos show an overview of the location looking east and west, respectively.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335543



**Photo 3:** Photos showing erosion and sediment migration on the northeast portion of the location. Stormwater controls appear to be missing or insufficient; comply with Rule 1002.f.



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335543



**Photo 4:** Photos showing a culvert along the access road. Sediment deposition and vegetative debris appears to be reducing capacity; install or maintain stormwater BMP's.



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335543



**Photo 5:** Photos showing the southern and northern interim areas, respectively. Crested wheatgrass, Sandberg bluegrass, smooth brome have established in some portions of the location. Other portions of the location are dominated by cheatgrass. Interim areas are In Process.



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335543



**Photo 6:** Ponded water was observed at the entrance to the location; gravel appeared sparse in some areas of the working pad surface. Maintenance is recommended.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335543



**Photo 7:** An unknown liquid was observed in some cellars at the location after adverse weather and seasonal rains; a follow-up inspection will be conducted to determine if liquids persist and require removal.



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources