

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON 41-8D (PARACHUTE CREEK 41-8D)

Location #: 324198



Photo # 590 From entrance to location




Photo # 591 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON 41-8D (PARACHUTE CREEK 41-8D)

Location #: 324198



Photo # 592 Location




Photo # 593 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON 41-8D (PARACHUTE CREEK 41-8D)

Location #: 324198



Photo # 594 Location



Photo # 595 Flowline heating insulation open ended/wildlife hazard/available for entry by wildlife

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON 41-8D (PARACHUTE CREEK 41-8D)

Location #: 324198



Photo # 596 Flowline heating insulation open ended/wildlife hazard/available for entry by wildlife



Photo # 597 Hole in secondary containment liner/liner needs maintenance

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON 41-8D (PARACHUTE CREEK 41-8D)

Location #: 324198



Photo # 598 Hole in secondary containment liner/liner needs maintenance



Photo # 599 Holes in secondary containment liner/liner needs maintenance

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON 41-8D (PARACHUTE CREEK 41-8D)

Location #: 324198



Photo # 600 Hole in secondary containment liner/liner needs maintenance



Photo # 601 Hole in secondary containment liner/liner needs maintenance

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON 41-8D (PARACHUTE CREEK 41-8D)

Location #: 324198



Photo # 602 Hole in secondary containment liner/liner needs maintenance



Photo # 603 Hole in secondary containment liner/liner needs maintenance

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON 41-8D (PARACHUTE CREEK 41-8D)

Location #: 324198



Photo # 604 Holes in secondary containment liner/liner needs maintenance



Photo # 605 Hole in secondary containment liner/liner needs maintenance

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON 41-8D (PARACHUTE CREEK 41-8D)

Location #: 324198



Photo # 606 Hole in secondary containment liner/liner needs maintenance



Photo # 607 Hole in secondary containment liner/liner needs maintenance

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON 41-8D (PARACHUTE CREEK 41-8D)

Location #: 324198



Photo # 608 Hole in secondary containment liner/liner needs maintenance



Photo # 609 Hole in secondary containment liner/liner needs maintenance

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON 41-8D (PARACHUTE CREEK 41-8D)

Location #: 324198



Photo # 610 Dead weeds/debris



Photo # 611 Dead weeds/debris