

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/23/2025

Submitted Date:

09/23/2025

Document Number:

698708090

FIELD INSPECTION FORM

Loc ID 307606 Inspector Name: Serna, Abe On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10705
Name of Operator: EVERGREEN NATURAL RESOURCES LLC
Address: 1875 LAWRENCE ST STE 1150
City: DENVER State: CO Zip: 80202

Findings:

6 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,	719-846-7898	cogcc.evergreen@enrllc.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
217888	WELL	PR	11/22/1999	CBM	071-06667	LORENCITO 4-8-34-66	PR

General Comment:

"This is a field audit of the scout card, related documents and the location."

Location

Overall Good:

Signs/Marker:

Type	OTHER		
Comment:	Well sign on meter house		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

						corrective date
Type: Progressive Cavity	# 1					
Comment:						
Corrective Action:					Date:	
Type: Ancillary equipment	# 1					
Comment:						
Corrective Action:					Date:	
Type: Vertical Separator	# 1					
Comment:						
Corrective Action:					Date:	
Type: Prime Mover	# 1					
Comment:						
Corrective Action:					Date:	
Type: Bradenhead	# 1					
Comment:						
Corrective Action:					Date:	
Type: Deadman # & Marked	# 4					
Comment:						
Corrective Action:					Date:	
Type: Gas Meter Run	# 1					
Comment:	"This is a field audit of the scout card, related documents and the location."					
Corrective Action:					Date:	

Venting:

Yes/No NO

Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 217888 Type: WELL API Number: 071-06667 Status: PR Insp. Status: PR

Producing Well

Comment: [PR](#)

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 10/08/2015 Annual Brhd Completed? _____

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: [Form 4 on file](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass	Culverts	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: NO Pit ID: Lat: Long:

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: Liner Condition:

Comment:

Corrective Action

Date:

Fencing:

Fencing Type: None Fencing Condition:

Comment:

Corrective Action

Date:

Netting:

Netting Type: Netting Condition:

Comment:

Corrective Action

Date:

Anchor Trench Present: Oil Accumulation: 2+ feet Freeboard:

Comment:

Corrective Action

Date:

ECMC Comments

Comment	User	Date
Routine Inspection	sernaa	09/23/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698708091	Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7248659