

FORM INSP Rev X/20	State of Colorado Energy and Carbon Management Commission 1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109	 	Inspection Date: <u>09/16/2025</u> Submitted Date: <u>09/17/2025</u> Document Number: <u>701104255</u>
FIELD INSPECTION FORM			

Loc ID 322423 Inspector Name: LONGWORTH, MIKE On-Site Inspection 2A Doc Num: _____

Status Summary:

THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments
4 Number of Corrective Actions
 Corrective Action Response Requested

Operator Information:

ECMC Operator Number: 10770
 Name of Operator: VISION ENERGY LLC
 Address: P O BOX 370
 City: IGNACIO State: CO Zip: 81137

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:


Contact Name	Phone	Email	Comment
Koch, Benjamin		bzkoch@blm.gov	
,		mrinc20@maralexinc.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
,		mollieo@maralexinc.com	
Kellerby, Shaun		shaun.kellerby@state.co.us	
,		pbechtolt@maralexinc.com	
Haverkamp, Curtis		curtis.haverkamp@state.co.us	
Popejoy, Dusty		dusty.popejoy@state.co.us	
Trujillo, Aaron		aaron.trujillo@state.co.us	
Cholas, Nick		nick.cholas@state.co.us	
Toews, Wesley		wtoews@blm.gov	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210462	WELL	SI	07/06/2021	GW	045-06218	DRY FORK FEDERAL 1-29	EG

General Comment:

Flowline Integrity Inspection
 Joint inspection with BLM Wesley Toews and Benjamin Koch CECMC EPS John Heil and Nick Cholas
 Location 322423 Dry Fork Federal-67S99W has a meter house still on site and offlocation flowline. There has been a stormwater slide event that has partially covered meter house and offlocation flowline and location.
 Previous inspection corrective action Copied from 02/03/2025 inspection 713400682 " Equipment on location is not in compliance with CECMC reclamation rules, refer to photos"
 Comply with CECMC reclamation rules CA Date 03/06/2025
 New Corrective Actions:
 Gathering line is not OOSLAT.
 Apply OOSLAT to out of service line(s) CA Date 9/18/2025
 Underground offlocation flowline marker is illegible.
 Comply with Rule 1102.g CA Date 10/03/2025
 No Form 6 subsequent report found in database for plugging operation.
 Submit Subsequent Form 6 for plug and abandonment of well in accordance with Rule 435.b CA Date 10/03/2025



Location

Overall Good:

Signs/Marker:

Type	OTHER		
Comment:	Underground offlocation flowline marker is illegible.		
Corrective Action:	Comply with Rule 1102.g	Date:	10/03/2025

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	<input type="text"/>
Corrective Action:	<input type="text"/>		

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type			corrective date
Flow Line	# 1		
Comment:	Gathering line not OOSLAT.		
Corrective Action:	Apply OOSLAT to out of service line(s)	Date:	09/18/2025
Other	# 2		
Comment:	Copied from 02/03/2025 inspection 713400682 " Equipment on location is not in compliance with CECMC reclamation rules, refer to photos" Meterhouse and gathering line have not been removed from location site.		
Corrective Action:	Comply with CECMC reclamation rules	Date:	03/06/2025

Venting:

Yes/No		
Comment:	<input type="text"/>	
Corrective Action:		Date:

Flaring:

Type		
Comment:	<input type="text"/>	
Corrective Action:		Date:

Inspected Facilities

Facility ID: 210462 Type: WELL API Number: 045-06218 Status: SI Insp. Status: EG

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: No Form 6 subsequent report found in database for plugging operation.

Corrective Action: Submit Subsequent Form 6 for plug and abandonment of well in accordance with Rule 435.b

Date: 10/03/2025

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404357773	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7240860
701104257	Flowline integrity inspection 701104255 photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7240859