

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/16/2025

Submitted Date:

09/17/2025

Document Number:

716900175

**FIELD INSPECTION FORM**

Loc ID 320276 Inspector Name: Huck, Keith On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 46290  
Name of Operator: KP KAUFFMAN COMPANY INC  
Address: 1700 LINCOLN ST STE 4550  
City: DENVER State: CO Zip: 80203

**Findings:**

- 7 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
		cogcc@kpk.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203332	WELL	SI	05/01/2021	OW	001-08841	JOHN WEIGANDT B 1	SI

**General Comment:**

[Follow Up Inspection from Document#717000448 and Document#715801429. Corrective Action for Weeds has not been addressed from these two inspections](#)

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	Adequate		
Corrective Action:		Date:	

**Good Housekeeping:**

Type	WEEDS		
Comment:	Weeds still not addressed from last two inspections. Please cut and remove thick and tall vegetation		
Corrective Action:	Comply with Rule 606	Date:	09/26/2025

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 203332 Type: WELL API Number: 001-08841 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment	User	Date
<p>ECMC Inspection Report Summary On Tuesday 9-16-2025 at approximately 10:14am. I, Inspector Chane Finkenbinder, Conducted an audit of the well scout card &amp; related forms followed by an onsite inspection: Operator: KP Kauffman Location # 320276 API # 05-001-08841 Well name: John Weigant B1 County: Adams Weather: Cloudy Temp: 76* Location: Dry While there, I observed a wellsite, SI at the time of inspection. During this inspection the following possible compliance issues were observed: 606 Housekeeping: Vegetation needs to be cut &amp; removed, CA date 9-26-2025. Any corrective actions from previous Inspections that have not been addressed are still applicable. See attached photos. A follow up on this site inspection will be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules.</p>	huckk	09/17/2025

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404357311	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7240498">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7240498</a>
716900176	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7240496">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7240496</a>