

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/22/2025

Submitted Date:

09/24/2025

Document Number:

719700119

FIELD INSPECTION FORM

Loc ID 310329 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

Findings:

- 11 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@chevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
292189	WELL	SI	04/01/2017	GW	123-26250	PAPPENHEIM USX AB 13-13	SI

General Comment:

*This is an audit of the scout card and related documents followed by a field audit.

Location

Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action:		Date:	

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Yellow LTSI tag posted.		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	CORRECTIVE ACTION(s) COMMENT: During this audit the following possible compliance issue(s) were observed: 1.) Emergency contact number at wellsite is invalid. Refer to Rule 605.d for guidance		
Corrective Action:	*Post VALID emergency contact number at wellsite. Comply with Rule 605.d. (30-days). See photo(s) #1. *Please attach photo(s) to FIRR to verify Corrective Action(s) have been resolved.		Date: 10/24/2025

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Iron panel.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears plumbed to surface.		
Corrective Action:		Date:	

Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.570041,-104.506598

Comment:	Centralized Battery serves 1 Location ID (310329). (Well(s): 1: Shut-In SI). Centralized Battery serves 1 Tank Battery Facility ID (Pending).	
Corrective Action:		Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 292189 Type: WELL API Number: 123-26250 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment: Shut-In | SI.
Prod valves shut.
Locked-Out, Tagged-Out | LOTO.
Yellow LTSI tag posted at wellsite.
ECMC records last prod: 03/2017.

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 04/10/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____
End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit						
Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
Comment: <input style="width:100%;" type="text"/> Corrective Action: <input style="width:100%;" type="text"/>						Date: _____
Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

ECMC Comments		
Comment	User	Date
This is a WELL audit. Well(s): 1: Shut-In SI. Battery: Inactive Shut-down. Centralized Battery serves 1 Location ID (310329). (Well(s): 1: Shut-In SI). Centralized Battery serves 1 Tank Battery Facility ID (Pending). Reference (Associated Well(s), Battery / Facility Audits): A.) Field Audit Report doc. #719700119 and/or Location ID #310329 for SI Well(s) info. B.) Field Audit Report doc. #719700121 and/or Location ID #310329 for Battery / Facility, Equipment info.	evinsb	09/24/2025
CECMC Audit Report Synopsis: On MON 09/22/2025 at approximately 14:35 hrs. I, Bret Evins, conducted an onsite audit at: Operator Name: NOBLE ENERGY INC Location Name: PAPPENHEIM USX AB-67N64W/13SWSW Location ID: 310329 Well Name(s) & API: Reference: See "Inspected Facilities" section on page 1 of this report. Location County: Weld County, Colorado Weather: Mostly Cloudy, dry. While there, I observed: Well(s): 1: Shut-In SI. Battery: Inactive Shut-down. *CORRECTIVE ACTION(s) COMMENT: Refer to pg 2, Signs/Marker section. Routine audit. *Any Corrective Actions from prior audits that have not been addressed remain applicable.	evinsb	09/24/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719700120	Audit photo(s)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7250406