

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/09/2025

Submitted Date:

09/24/2025

Document Number:

697602588

FIELD INSPECTION FORM

Loc ID: 460826 Inspector Name: Ahmadian, Alexander On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10646
Name of Operator: AXIS EXPLORATION LLC
Address: 555 17TH STREET SUITE 3700
City: DENVER State: CO Zip: 80202

Findings:

- 6 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Evans, Jacob		jevans@civiresources.com	
,		Inspections@civiresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
461314	OFF-LOCATION FLOWLINE	AC	03/28/2025		-	GORDON 13-19 1-A	EI
490326	SPILL OR RELEASE	CL	05/25/2025		-	GORDON 13-19 1-A	EI

General Comment:

This is an environmental inspection to determine progress on Spill ID 490326/Remediation Project No 39913. Any corrective actions from previous inspections, NOAVs, or COAs that have not been addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	STORAGE OF SUPL		
Comment:	Fencing supplies are stored on location.		
Corrective Action:	Operator shall comply with Housekeeping Rule 606.		Date: <u>10/01/2025</u>
Type	TRASH		
Comment:	Trash is scattered throughout the site.		
Corrective Action:	Comply with Housekeeping Rule 606.		Date: <u>10/01/2025</u>

Overall Good:

Spills:

Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	OTHER		
Comment:	Fencing around the excavation has fallen.		
Corrective Action:	Fencing is not in compliance. The operator is to maintain best management practices to control and contain all spills/releases of E&P waste to protect the environment, public health, safety and welfare and the environment as required by rule 913.b(5)B.i which requires that Operators will fence or cover open remediation excavations to prevent access when sites are not attended.		Date: <u>10/01/2025</u>

Venting:

Yes/No		
Comment:		
Corrective Action:		Date: _____

Flaring:

Type		
Comment:		
Corrective Action:		Date: _____

Inspected Facilities

Facility ID: 461314 Type: OFF- API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 490326 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Environmental

Waste Management:

Type	Management	Condition	GPS (Lat)	(Long)
Oily Soil		Inadequate		
Comment	Multiple unmarked, unlined, and unbermed stockpiles were observed on location.			
Corrective Action	E&P Waste shall be properly stored, handled, transported, treated, recycled, or disposed per Rule 905.			Date: 10/01/2025

Spill/Remediation:

Comment:	Remedial excavation is open. The fencing around the excavation has fallen and is in need of repair.		
Corrective Action:		Date:	_____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697602589	Photolog	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7250943