

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/17/2025

Submitted Date:

09/17/2025

Document Number:

714202512

FIELD INSPECTION FORM

Loc ID 332631 Inspector Name: Santistevan, Brittani On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 69175
Name of Operator: PDC ENERGY INC
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

Findings:

- 12 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|----------------|-------|---------------------------|---------------------------------|
| , | | cogccinspection@pdce.com | All Inspections |
| White, Jeffery | | jeffery.white@chevron.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------|-------------|
| 245364 | WELL | PR | 11/01/2017 | GW | 123-13159 | HARD-FOUGHT 1-35 | PR |
| 270294 | WELL | PR | 04/01/2025 | OW | 123-21859 | RODRIGUEZ 4-35 | PR |

General Comment:

[This is an audit of HARD FOUGHT 1-35, RODRIGUEZ 4-35 scout card and related documents followed by a field inspection.](#)

Location

Overall Good:

Signs/Marker:

| | | | |
|--------------------|----------------------|--|-------|
| Type | BATTERY | | |
| Comment: | ADEQUATE | | |
| Corrective Action: | | | Date: |
| Type | WELLHEAD | | |
| Comment: | ADEQUATE | | |
| Corrective Action: | | | Date: |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | ADEQUATE | | |
| Corrective Action: | | | Date: |

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

| Type | Area | Volume | | |
|------|------|--------|--|--|
| | | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

| | | | |
|--------------------|----------|--|-------|
| Type | WELLHEAD | | |
| Comment: | PANEL | | |
| Corrective Action: | | | Date: |

Equipment:

| Type | | | corrective date |
|-----------------------------------|-----|--|-----------------|
| Type: Gas Meter Run | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Horizontal Heated Separator | # 2 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Bradenhead | # 2 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Emission Control Device | # 2 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Plunger Lift | # 2 | | |

| | | | |
|-----------------------|-----|--|-------|
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Bird Protectors | # 4 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| CRUDE OIL | 1 | OTHER | STEEL AST | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | 315 BBLs | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Metal | Adequate | Walls Sufficent | Base Sufficient | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | |

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|----------------|---------|--------|
| PRODUCED WATER | 1 | 100 BBLs | PBV FIBERGLASS | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|--------------------------------------|---------------------|---------------------|-------------|
| | | | | |
| Comment: | Shares containment with other tanks. | | | |
| Corrective Action: | | | | |

Venting:

| | | |
|--------------------|----|--|
| Yes/No | NO | |
| Comment: | | |
| Corrective Action: | | |

Flaring:

| | |
|------|--|
| Type | |
|------|--|

| | |
|--------------------|-------|
| Comment: | |
| Corrective Action: | Date: |

Inspected Facilities

Facility ID: 245364 Type: WELL API Number: 123-13159 Status: PR Insp. Status: PR

Producing Well

Comment: PR; valves appear to be in the open position.

Corrective Action: Date:

BradenHead

Date of Last Brhd Test: 07/07/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____
 End Surf Csg Pressure: 0

Comment:

Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 270294 Type: WELL API Number: 123-21859 Status: PR Insp. Status: PR

Producing Well

Comment: PR; valves appear to be in the open position.

Corrective Action: Date:

BradenHead

Date of Last Brhd Test: 07/07/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____
 End Surf Csg Pressure: 0

Comment:

Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | Fail | Gravel | Pass | | | |

Comment: [it appears to be erosion on multiple areas of location. See attached photos.](#)

Corrective Action: [Install proper BMP's per Rule 1002.f.\(2\).C.](#)

Date: 10/31/2025

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

| Comment | User | Date |
|---|----------|------------|
| <p>ECMC Audit Report Summary WEATHER CONDITIONS: sunny, wet ground. On Wednesday, September 17, 2025 at approximately 1100, I, Inspector Brittani Santistevan, conducted an on-site inspection at HAR FOUGHT 1-35, RODRIGUEZ 4-35 (PDC Energy), at location ID: 332631 in WELD COUNTY, Colorado. While there, I observed a producing facility. During this inspection the following possible compliance issues were observed: 1. It appears to be erosion on multiple areas of the location. Install proper BMPs per Rule 1002.f.(2).C. (Corrective Action Date: October 31, 2025) See attached photo #4, 5, 10, 11, 13-15.</p> <p>A follow up on this site audit needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules. This is a summary of the audit report.</p> | santistb | 09/17/2025 |

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 404359079 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7242237 |
| 714202513 | Photo | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7242232 |