

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/17/2025

Submitted Date:

09/18/2025

Document Number:

714202514

FIELD INSPECTION FORM

Loc ID: 329009 Inspector Name: Santistevan, Brittani On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 69175
Name of Operator: PDC ENERGY INC
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

Findings:

- 12 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
White, Jeffery		jeffery.white@chevron.com	All Inspections
,		cogccinspection@pdce.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
248939	WELL	SI	05/01/2023	GW	123-16741	RAISLEY 21-34	SI

General Comment:

This is an audit of RAISLEY 21-34 scout card and related documents followed by a field inspection.

Location

Lease Road:			
Type	Access		
comment:	ACCESS ROAD APPEARS TO HAVE EROSION. SEE ATTACHED PHOTO		
Corrective Action		Date:	

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	SIGN APPEARS TO BE DAMAGED AND NO LONGER LEGIBLE. SEE ATTACHED PHOTO.		
Corrective Action:	INSTALL SIGN TO COMPLY WITH RULE 605.D.	Date:	10/18/2025
Type	TANK LABELS/PLACARDS		
Comment:	ADEQUATE		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	OPERATOR'S NAME IS NO LONGER LEGIBLE, APPEARS TO HAVE SOME DAMAGE. SEE ATTACHED PHOTO.		
Corrective Action:	INSTALL SIGN TO COMPLY WITH RULE 605.E.	Date:	10/18/2025

Emergency Contact Number:		
Comment:	<input style="width: 100%;" type="text"/>	
Corrective Action:	<input style="width: 100%;" type="text"/>	Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	PANEL		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	

Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	BV CONCRETE		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	48 BBLs	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	SHARES CONTAINMENT WITH OTHER TANKS.			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		
		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 248939 Type: WELL API Number: 123-16741 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment: SI; Form 6A in well file.

Corrective Action: Date:

BradenHead

Date of Last Brhd Test: 07/01/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit						
Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Fail			
Comment: it appears to be erosion to lease road. see attached photo.						Date: 10/18/2025
Corrective Action: INSTALL BMPs TO COMPLY WITH RULE 1002.F.(2).C.						
Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

ECMC Comments		
Comment	User	Date
<p>ECMC Audit Report Summary WEATHER CONDITIONS: sunny, wet ground. On Wednesday, September 17, 2025 at approximately 1400, I, Inspector Brittani Santistevan, conducted an on-site inspection at RAISELY 21-34 (PDC Energy), at location ID: 329009 in WELD COUNTY, Colorado. While there, I observed a shut-in facility. During this inspection the following possible compliance issues were observed:</p> <ol style="list-style-type: none"> 1. It appears to be some erosion to the lease road. Install BMPs to comply with Rule 1002.f.(2).C. (Corrective Action Date: October 18, 2025) See attached photo #1-2. 2. It appears that the operator's name on the tank battery sign is no longer legible and sign is damaged. Install sign to comply with Rule 605.e. (Corrective Action Date: October 18,2025) See attached photo #7. 3. It appears the wellhead sign is no longer legible and is damaged. Install sign to comply with Rule 605.d. (Corrective Action Date: October 18, 2025) See attached photo #4. <p>A follow up on this site audit needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules. This is a summary of the audit report.</p>	santistb	09/18/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404359084	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7242240
714202517	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7242233