

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/18/2025

Submitted Date:

09/25/2025

Document Number:

713401094

**FIELD INSPECTION FORM**

Loc ID 316088 Inspector Name: Popejoy, Dusty On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10539  
Name of Operator: UTAH GAS OP LTD DBA UTAH GAS CORP  
Address: 734 MAIN STREET 3RD FLOOR  
City: GRAND JUNCTION State: CO Zip: 81501

**Findings:**

12 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name   | Phone | Email                       | Comment |
|----------------|-------|-----------------------------|---------|
| GAS, UTAH      |       | inspections@utahgascorp.com |         |
| Koch, Benjamin |       | bzkoch@blm.gov              |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name          | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------------|-------------|
| 232079      | WELL | PR     | 01/11/1995  | GW         | 103-09750 | CATHEDRAL FEDERAL 33-2 | PR          |

**General Comment:**

This is a Field Inspection/audit of the scout card, related documents and the location.

**Location**

|                    |        |  |       |
|--------------------|--------|--|-------|
| <b>Lease Road:</b> |        |  |       |
| Type               | Access |  |       |
| comment:           | Access |  |       |
| Corrective Action  | L      |  | Date: |

Overall Good:

|                      |  |  |       |
|----------------------|--|--|-------|
| <b>Signs/Marker:</b> |  |  |       |
| Type                 | TANK LABELS/PLACARDS   |  |       |
| Comment:             |  |  |       |
| Corrective Action:   |  |  | Date: |
| Type                 | OTHER  |  |       |
| Comment:             | Sign on separator  |  |       |
| Corrective Action:   |  |  | Date: |
| Type                 | WELLHEAD   |  |       |
| Comment:             |  |  |       |
| Corrective Action:   |  |  | Date: |
| Type                 | OTHER  |  |       |
| Comment:             | Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks. |  |       |
| Corrective Action:   |  |  | Date: |
| Type                 | BATTERY  |  |       |
| Comment:             |  |  |       |
| Corrective Action:   |  |  | Date: |

|                                  |                  |             |
|----------------------------------|------------------|-------------|
| <b>Emergency Contact Number:</b> |                  |             |
| Comment:                         | 970-693-6021/911 |             |
| Corrective Action:               |                  | Date: _____ |

Overall Good:

| <b>Spills:</b> |      |        |  |
|----------------|------|--------|--|
| Type           | Area | Volume |  |

In Containment: No \_\_\_\_\_

Comment: \_\_\_\_\_

Multiple Spills and Releases?

|                    |  |     |                 |
|--------------------|--|-----|-----------------|
| <b>Equipment:</b>  |  |     | corrective date |
| Type:              | Horizontal Heated Separator  | # 1 |                 |
| Comment:           |  |     |                 |
| Corrective Action: |  |     | Date:           |
| Type:              | Bradenhead   | # 1 |                 |
| Comment:           | No form of pressure monitoring equipment. Bradenhead valve is accessible |     |                 |
| Corrective Action: |  |     | Date:           |

|                          |     |  |       |
|--------------------------|-----|--|-------|
| Type: Deadman # & Marked | # 4 |  |       |
| Comment:                 |     |  |       |
| Corrective Action:       |     |  | Date: |
| Type: Bird Protectors    | # 2 |  |       |
| Comment:                 |     |  |       |
| Corrective Action:       |     |  | Date: |
| Type: Gas Meter Run      | # 1 |  |       |
| Comment:                 |     |  |       |
| Corrective Action:       |     |  | Date: |

**Tanks and Berms:**

| Contents           | #                                | Capacity | Type     | Tank ID | SE GPS |
|--------------------|----------------------------------|----------|----------|---------|--------|
| PRODUCED WATER     | 1                                | <50 BBLs | Open Top |         |        |
| Comment:           | Tank not equipped with telemetry |          |          |         |        |
| Corrective Action: |                                  |          |          |         | Date:  |

**Paint**

|                  |            |  |
|------------------|------------|--|
| Condition        | Inadequate |  |
| Other (Content)  |            |  |
| Other (Capacity) | 30 bbls    |  |
| Other (Type)     |            |  |

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Metal              | Adequate | Walls Sufficient    |                     |             |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

**Venting:**

|                    |    |       |
|--------------------|----|-------|
| Yes/No             | NO |       |
| Comment:           |    |       |
| Corrective Action: |    | Date: |

**Flaring:**

|                    |       |
|--------------------|-------|
| Type               |       |
| Comment:           |       |
| Corrective Action: | Date: |

**Inspected Facilities**

Facility ID: 232079 Type: WELL API Number: 103-09750 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing well](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment          |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|------------------|
| Compaction       |                 |                         |                       |               |                          | Light compaction |
| Berms            |                 |                         |                       |               |                          |                  |
|                  |                 | Compaction              |                       |               |                          | Light compaction |
| Ditches          |                 |                         |                       |               |                          |                  |

Comment: Operator is responsible for maintaining Best Management Practices (BMP's) to control vehicle tracking and potential sediment discharges from operational roads, well pads, and other unpaved surfaces.

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**ECMC Comments**

| Comment  | User     | Date       |
|--|----------|------------|
| <p><a href="#">CECMC Inspection/Audit Report Summary</a></p> <p>On 09/18/2025 at approximately 11:23 hours, Compliance Inspector Dusty Popejoy conducted an on-site inspection/audit at UTAH GAS OP LTD DBA UTAH GAS CORP CATHEDRAL FEDERAL #33-2 PAD at Location ID #316088 in Rio Blanco County, Colorado.</p> <p>This location is within or in close proximity to a Parks and Wildlife (CPW) District with High Priority, NSO, Density Habitat regulations.</p> <p>While there, I observed normal production operations.</p> <p>This is a summary of inspection/audit report.</p> | popejoyd | 09/24/2025 |

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description                       | URL   |
|--------------|-----------------------------------|---|
| 713401095    | 713401094 Inspection-Audit Photos | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7253810">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7253810</a> |