

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/25/2025

Submitted Date:

09/25/2025

Document Number:

698708119

**FIELD INSPECTION FORM**

Loc ID 321144 Inspector Name: Serna, Abe On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10560  
Name of Operator: WEST TEXAS OPERATING CO LLC DBA XTREME  
Address: PO BOX 2326  
City: VICTORIA State: TX Zip: 77902

**Findings:**

- 6 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name | Phone                 | Email           | Comment |
|--------------|-----------------------|-----------------|---------|
| Hahn, Mike   | (361) 570-1600<br>x24 | mhahn@xeogc.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 206148      | WELL | PR     | 12/12/1997  | GW         | 009-06564 | MCKINLEY 2-20 | PR          |

**General Comment:**

[Routine UIC Inspection](#)

**Location**

Overall Good:

**Signs/Marker:**

|                    |          |       |  |
|--------------------|----------|-------|--|
| Type               | WELLHEAD |       |  |
| Comment:           | Adequate |       |  |
| Corrective Action: |          | Date: |  |

**Emergency Contact Number:**

|                    |                      |  |             |
|--------------------|----------------------|--|-------------|
| Comment:           | <input type="text"/> |  |             |
| Corrective Action: | <input type="text"/> |  | Date: _____ |

**Good Housekeeping:**

|                    |  |       |            |
|--------------------|--|-------|------------|
| Type               | WEEDS  |       |            |
| Comment:           | Weeds around tanks & location need to be cut & removed |       |            |
| Corrective Action: | Comply with rule 605                                   | Date: | 10/02/2025 |

Overall Good:

**Spills:**

| Type | Area | Volume |  |  |
|------|------|--------|--|--|
|      |      |        |  |  |

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

| Type                      |     |       | corrective date |
|---------------------------|-----|-------|-----------------|
| Type: Pump Jack           | # 1 |       |                 |
| Comment:                  |     |       |                 |
| Corrective Action:        |     | Date: |                 |
| Type: Ancillary equipment | # 1 |       |                 |
| Comment:                  |     |       |                 |
| Corrective Action:        |     | Date: |                 |
| Type: Bradenhead          | # 1 |       |                 |
| Comment:                  |     |       |                 |
| Corrective Action:        |     | Date: |                 |
| Type: Gas Meter Run       | # 1 |       |                 |
| Comment:                  |     |       |                 |
| Corrective Action:        |     | Date: |                 |

**Tanks and Berms:**

| Contents           | # | Capacity | Type           | Tank ID | SE GPS |
|--------------------|---|----------|----------------|---------|--------|
| PRODUCED WATER     | 2 | 200 BBLS | FIBERGLASS AST |         | ,      |
| Comment:           |   |          |                |         |        |
| Corrective Action: |   | Date:    |                |         |        |

**Paint**

|           |          |
|-----------|----------|
| Condition | Adequate |
|-----------|----------|

|                  |  |
|------------------|--|
| Other (Content)  |  |
| Other (Capacity) |  |
| Other (Type)     |  |

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
|                    |          |                     |                     |             |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

**Venting:**

| Yes/No             | NO |       |  |
|--------------------|----|-------|--|
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

**Flaring:**

|                    |       |
|--------------------|-------|
| Type               |       |
| Comment:           |       |
| Corrective Action: | Date: |

**Inspected Facilities**

Facility ID: 206148 Type: WELL API Number: 009-06564 Status: PR Insp. Status: PR

**Producing Well**

Comment: [PR](#)

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 02/28/2024 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment: [Submit files](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

| Comment                            | User   | Date       |
|------------------------------------|--------|------------|
| <a href="#">Routine Inspection</a> | sernaa | 09/25/2025 |

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL   |
|--------------|-------------|---|
| 698708120    | Photo       | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7254457">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7254457</a> |