

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/25/2025

Submitted Date:

09/25/2025

Document Number:

693808945

FIELD INSPECTION FORM

Loc ID 438499 Inspector Name: BROWNING, CHUCK On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10433
Name of Operator: LARAMIE ENERGY LLC
Address: 1700 LINCOLN ST STE 3950
City: DENVER State: CO Zip: 80203

Findings:

- 38 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Hylton, Monika	(970) 712-3698	mhylton@laramie-energy.com	
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
301411	WELL	PR	11/26/2015	GW	077-09939	Piceance 28-15M	PR
301412	WELL	PR	02/18/2016	GW	077-09940	Piceance 28-21W	PR
301414	WELL	PR	02/18/2016	GW	077-09942	Piceance 28-21M	PR
301415	WELL	PR	02/17/2016	GW	077-09943	Piceance 28-20W	PR
301416	WELL	PR	09/01/2020	GW	077-09944	Piceance 28-20M	PR
301417	WELL	PR	02/17/2016	GW	077-09945	Piceance 28-19W	PR
301418	WELL	PR	09/01/2020	GW	077-09946	Piceance 28-19M	PR
301419	WELL	PR	01/02/2016	GW	077-09947	Piceance 28-18W	PR
301420	WELL	PR	01/05/2016	GW	077-09948	Piceance 28-18M	PR
301421	WELL	PR	01/01/2016	GW	077-09949	Piceance 28-17W	PR
301422	WELL	PR	01/06/2016	GW	077-09950	Piceance 28-17M	PR
301423	WELL	PR	12/03/2015	GW	077-09951	Piceance 28-16W	PR
301424	WELL	PR	11/28/2015	GW	077-09952	Piceance 28-16M	PR
301425	WELL	PR	11/23/2016	GW	077-09953	Piceance 28-15W	PR
301426	WELL	PR	12/30/2015	GW	077-09954	Piceance 28-14W	PR
301427	WELL	PR	01/07/2016	GW	077-09955	Piceance 28-14M	PR
301428	WELL	PR	10/24/2015	GW	077-09956	Piceance 28-13W	PR
411976	WELL	PR	10/28/2015	GW	077-10060	Piceance 28-13M	PR
438457	WELL	PR	09/19/2015	GW	077-10220	Piceance 28-11W	PR
438458	WELL	PR	10/27/2015	GW	077-10221	Piceance 28-12W	PR

438859	WELL	PR	10/20/2015	GW	077-10223	Piceance 28-12M	PR
438860	WELL	PR	10/20/2015	GW	077-10224	Piceance 28-11M	PR

General Comment:

[ECMC Inspection/Audit Report Summary](#)

On September 9, 2025, ECMC Compliance Specialist Chuck Browning, conducted an onsite inspection/audit for LARAMIE ENERGY LLC 10433 on the Piceance 28-11 Pad, Loc ID#438499, in Mesa County, Colorado.

Normal production operations were observed.

During the inspection/audit, the following compliance issues were observed:

- 1) Sign at wellhead location entrance damaged 605.g

Any corrective action(s) from previous inspection that have not been addressed are still applicable

Location

Lease Road:			
Type	Main		
comment:	330 E Rd		
Corrective ActionL			Date:
Type	Access		
comment:	Groundhog Gulch Rd		
Corrective ActionL			Date:

Overall Good:

Signs/Marker:			
Type	BATTERY		
Comment:	Sign at production location entrance. Pad Approx 300' W of wellhead location.		
Corrective Action:			Date:
Type	BATTERY		
Comment:	Sign at wellhead location entrance damaged		
Corrective Action:	Install sign or correct sign per rule 605		Date: 11/28/2025
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:

Comment: 800-891-6191

Corrective Action: _____ Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment: _____

Multiple Spills and Releases?

Equipment:			corrective date
Type: Flow Line	# 2		
Comment:	1-3" rise (blinded) & 1-6" with valves (blinded)		
Corrective Action:			Date:
Type: Plunger Lift	# 20		
Comment:	22 total		
Corrective Action:			Date:

Type: Bradenhead	# 20	
Comment:	22 total	
Corrective Action:		Date:
Type: Ancillary equipment	# 4	
Comment:	Chemical injectors with secondary containment	
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 20	
Comment:	22 total. 4-5 place units & 1-2 place unit	
Corrective Action:		Date:
Type: Pig Station	# 1	
Comment:		
Corrective Action:		Date:
Type: Bird Protectors	# 6	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	OTHER	STEEL AST		39.247890,-107.778090
Comment:	On wellhead location				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	500 gal
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	3	400 BBLs	HEATED STEEL AST		39.248337,-107.779004
Comment:	On production location				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 301411 Type: WELL API Number: 077-09939 Status: PR Insp. Status: PR

Producing Well

Comment: Plunger lift

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 08/03/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 301412 Type: WELL API Number: 077-09940 Status: PR Insp. Status: PR

Producing Well

Comment: Plunger lift

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 08/03/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 301414 Type: WELL API Number: 077-09942 Status: PR Insp. Status: PR

Producing Well

Comment: Plunger lift

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 08/03/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 301415 Type: WELL API Number: 077-09943 Status: PR Insp. Status: PR

Producing Well

Comment: Plunger lift

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 08/03/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 301416 Type: WELL API Number: 077-09944 Status: PR Insp. Status: PR

Producing Well

Comment: Plunger lift

Corrective Action: _____

Date: _____

BradenHead

Date of Last Brhd Test: 08/03/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 301417 Type: WELL API Number: 077-09945 Status: PR Insp. Status: PR

Producing Well

Comment: Plunger lift

Corrective Action: _____

Date: _____

BradenHead

Date of Last Brhd Test: 08/03/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 301418 Type: WELL API Number: 077-09946 Status: PR Insp. Status: PR

Producing Well

Comment: Plunger lift

Corrective Action: _____

Date: _____

BradenHead

Date of Last Brhd Test: 08/03/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 301419 Type: WELL API Number: 077-09947 Status: PR Insp. Status: PR

Producing Well

Comment: Plunger lift

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 08/03/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 301420 Type: WELL API Number: 077-09948 Status: PR Insp. Status: PR

Producing Well

Comment: Plunger lift

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 08/03/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 50 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 301421 Type: WELL API Number: 077-09949 Status: PR Insp. Status: PR

Producing Well

Comment: Plunger lift

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 08/03/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 301422 Type: WELL API Number: 077-09950 Status: PR Insp. Status: PR

Producing Well

Comment: Plunger lift

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 08/03/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 5 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 301423 Type: WELL API Number: 077-09951 Status: PR Insp. Status: PR

Producing Well

Comment: Plunger lift

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 07/11/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 301424 Type: WELL API Number: 077-09952 Status: PR Insp. Status: PR

Producing Well

Comment: Plunger lift

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 08/03/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 301425 Type: WELL API Number: 077-09953 Status: PR Insp. Status: PR

Producing Well

Comment: Plunger lift

Corrective Action: _____

Date: _____

BradenHead

Date of Last Brhd Test: 08/03/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 301426 Type: WELL API Number: 077-09954 Status: PR Insp. Status: PR

Producing Well

Comment: Plunger lift

Corrective Action: _____

Date: _____

BradenHead

Date of Last Brhd Test: 08/03/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 301427 Type: WELL API Number: 077-09955 Status: PR Insp. Status: PR

Producing Well

Comment: Plunger lift

Corrective Action: _____

Date: _____

BradenHead

Date of Last Brhd Test: 08/03/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 301428 Type: WELL API Number: 077-09956 Status: PR Insp. Status: PR

Producing Well

Comment: Plunger lift

Corrective Action: _____

Date: _____

BradenHead

Date of Last Brhd Test: 08/03/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 411976 Type: WELL API Number: 077-10060 Status: PR Insp. Status: PR

Producing Well

Comment: Plunger lift

Corrective Action: _____

Date: _____

BradenHead

Date of Last Brhd Test: 08/03/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 438457 Type: WELL API Number: 077-10220 Status: PR Insp. Status: PR

Producing Well

Comment: Plunger lift

Corrective Action: _____

Date: _____

BradenHead

Date of Last Brhd Test: 08/03/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____
 End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 438458 Type: WELL API Number: 077-10221 Status: PR Insp. Status: PR

Producing Well

Comment: Plunger lift

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 08/03/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 115 Fluid Type: _____
 End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 438859 Type: WELL API Number: 077-10223 Status: PR Insp. Status: PR

Producing Well

Comment: Plunger lift

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 08/03/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 110 Fluid Type: _____
 End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 438860 Type: WELL API Number: 077-10224 Status: PR Insp. Status: PR

Producing Well

Comment: Plunger lift

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 08/03/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Ditches	Pass			
Berms	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	Secondary containment of chemicals

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
Damaged sign at location entrance	browninc	09/25/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693808947	Inspection photos 9/9/2025	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7254548