

Storm Water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC AP 22-24-696 Pad
Location ID: 335485



**Location Overview: Location is within Black Bear Habitat area
& in close proximity to High Priority/Density Habitat areas.
Location is approximately 377 yards from Rule 411a Surface
Water External Buffer**

Section/Township/Range: 24 6S96W

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC AP 22-24-696 Pad
Location ID: 335485

68° E
Garfield County



North West corner of location.

171° S
Garfield County



North East corner of location.

Garfield County



South West corner of location.

Garfield County



South East corner of location.

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC AP 22-24-696 Pad
Location ID: 335485



Photo # 2548 Failure to maintain chemical BMP – Chemical tank containment approximately 3/4 full of fluid/BMP insufficient to contain possible spill

Photo # 2549 Failure to maintain chemical BMP – Chemical tank containment approximately 3/4 full of fluid/BMP insufficient to contain possible spill (Additionally standing fluid on containment constitutes a wildlife hazard)

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC AP 22-24-696 Pad
Location ID: 335485



Photo # 2550 Failure to maintain chemical BMP – Chemical tank containment approximately 3/4 full of fluid/BMP insufficient to contain possible spill

Photo # 2551 Failure to maintain chemical BMP – Chemical tank containment approximately 3/4 full of fluid/BMP insufficient to contain possible spill (Additionally standing fluid on containment constitutes a wildlife hazard)