

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC AP 22-24-696 Pad

Location ID: 335485



Photo # 2514 From entrance to location

Photo # 2515 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC AP 22-24-696 Pad

Location ID: 335485



Photo # 2516 Location



Photo # 2517 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC AP 22-24-696 Pad

Location ID: 335485




Photo # 2518 Location



Photo # 2519 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC AP 22-24-696 Pad

Location ID: 335485




Photo # 2520 Location

Photo # 2521 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC AP 22-24-696 Pad

Location ID: 335485



Photo # 2522 Location



Photo # 2523 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC AP 22-24-696 Pad

Location ID: 335485



Photo # 2524 Unused flowline lacks lockout tagout (OOSLAT)



Photo # 2525 Unused flowline lacks lockout tagout (OOSLAT)

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC AP 22-24-696 Pad

Location ID: 335485



Photo # 2526 Unused flowline lacks lockout tagout (OOSLAT)

Photo # 2527 Unused flowline lacks lockout tagout (OOSLAT)

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC AP 22-24-696 Pad

Location ID: 335485



Photo # 2528 Unused flowline lacks lockout tagout (OOSLAT)

Photo # 2529 Unused flowline lacks lockout tagout (OOSLAT)

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC AP 22-24-696 Pad

Location ID: 335485



Photo # 2530 Unused flowline lacks lockout tagout (OOSLAT)

Photo # 2531 Unused flowline lacks lockout tagout (OOSLAT)

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC AP 22-24-696 Pad

Location ID: 335485



Photo # 2532 Unused flowline lacks lockout tagout (OOSLAT)



Photo # 2533 Unused flowline lacks lockout tagout (OOSLAT)

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC AP 22-24-696 Pad

Location ID: 335485



Photo # 2534 Open ended piping near wellhead/wildlife hazard/available for entry by wildlife



Photo # 2535 Open ended piping near wellhead/wildlife hazard/available for entry by wildlife

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC AP 22-24-696 Pad

Location ID: 335485



Photo # 2536 Unused equipment



Photo # 2537 Unused equipment

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC AP 22-24-696 Pad

Location ID: 335485



Photo # 2538 Unused equipment



Photo # 2539 Unmarked deadman

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC AP 22-24-696 Pad

Location ID: 335485



Photo # 2540 Same unmarked deadman



Photo # 2541 Same unmarked deadman

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC AP 22-24-696 Pad

Location ID: 335485



Photo # 2542 Open ended load line



Photo # 2543 Unmarked deadman

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC AP 22-24-696 Pad

Location ID: 335485



Photo # 2544 Same unmarked deadman

Photo # 2545 Same unmarked deadman

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC AP 22-24-696 Pad

Location ID: 335485



Photo # 2546 PRV vent line on tank burner does not comply with CECMC pressure safety device rules

Photo # 2547 PRV vent line on tank burner does not comply with CECMC pressure safety device rules