

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/17/2025

Submitted Date:

09/19/2025

Document Number:

713401086

FIELD INSPECTION FORM

Loc ID 314651 Inspector Name: Popejoy, Dusty On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10539
Name of Operator: UTAH GAS OP LTD DBA UTAH GAS CORP
Address: 734 MAIN STREET 3RD FLOOR
City: GRAND JUNCTION State: CO Zip: 81501

Findings:

- 14 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Koch, Benjamin		bzkoch@blm.gov	
Kellerby, Shaun		shaun.kellerby@state.co.us	
GAS, UTAH		inspections@utahgascorp.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
229197	WELL	PR	06/25/1961	GW	103-06284	DOUGLAS CREEK UNIT 7	PR

General Comment:

[This is a Field Inspection/audit of the scout card, related documents and the location.](#)

Location

Lease Road:

Type	Access				
comment:	Access				
Corrective ActionL				Date:	

Overall Good:

Signs/Marker:

Type	TANK LABELS/PLACARDS				
Comment:					
Corrective Action:				Date:	
Type	BATTERY				
Comment:	Battery sign contains inaccurate nearest public road information Sign on meter house				
Corrective Action:	Comply with CECMC Signage rules			Date:	09/05/2025
Type	WELLHEAD				
Comment:					
Corrective Action:				Date:	

Emergency Contact Number:

Comment:	970-693-6021/911				
Corrective Action:				Date:	

Overall Good:

Spills:

Type	Area	Volume			
In Containment:	No				
Comment:	<input style="width: 100%;" type="text"/>				
<input type="checkbox"/> Multiple Spills and Releases?					

Equipment:

					corrective date
Type: Bird Protectors	# 1				
Comment:					
Corrective Action:				Date:	
Type: Gas Meter Run	# 1				
Comment:					
Corrective Action:				Date:	
Type: Bradenhead	# 1				
Comment:	No form of pressure monitoring equipment. Bradenhead valve is accessible				
Corrective Action:				Date:	
Type: Plunger Lift	# 1				
Comment:	Well on plunger lift				
Corrective Action:				Date:	

Type: Ancillary equipment	# 1	
Comment:	Flameless gas infrared catalytic heater	
Corrective Action:		Date:
Type: Deadman # & Marked	# 4	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLs	Open Top		
Comment:	Tank not equipped with telemetry				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	30 bbls
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent		
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 229197 Type: WELL API Number: 103-06284 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing well on plunger lift](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
		Ditches				
Other	Fail					Failure to minimize erosion & sediment
		Berms				
Ditches						
Compaction						Light compaction
		Compaction				Light compaction

Comment: 1. Failure to minimize erosion & transport of sediment - Erosion & transport of sediment on outslope/sediment migrating onto location/insufficient BMP's

Corrective Action: **Comply with CECMC Stormwater rules**

Date: 08/20/2025

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>CECMC Inspection/Audit Report Summary</p> <p>On 09/17/2025 at approximately 12:48 hours, Compliance Inspector Dusty Popejoy conducted a follow up inspection/audit at UTAH GAS OP LTD DBA UTAH GAS CORP DOUGLAS CREEK UNIT #7 PAD at Location ID #314651 in Rio Blanco County, Colorado.</p> <p>Please refer to inspection/audit 713400953 conducted on 07/29/2025, 2 of 4 corrective actions have been completed. Failure to minimize erosion & transport of sediment/insufficient BMP's & Battery sign contains inaccurate nearest public road information are not resolved and corrective action dates remain the same.</p> <p>This location is within or in close proximity to a Parks and Wildlife (CPW) District with High Priority, NSO, Density Habitat regulations.</p> <p>While there, I observed normal production operations.</p> <p>During the inspection/audit, the following compliance issues were observed:</p> <ol style="list-style-type: none"> 1. Stormwater - Failure to minimize erosion & transport of sediment/insufficient BMP's with a CA date of 08/20/2025 2. Signs/Marker - Battery sign contains inaccurate nearest public road information with a CA date of 09/5/2025 <p>A follow-up on this site inspection/audit will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.</p> <p>This is a summary of inspection/audit report.</p>	popejoyd	09/19/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404361595	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7245142
713401087	713401086 Inspection- Audit Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7245137