

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/18/2025

Submitted Date:

09/19/2025

Document Number:

715202968

FIELD INSPECTION FORM

Loc ID 321823 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 37230
Name of Operator: HALDE OIL INC
Address: 46321 HWY 24
City: BURLINGTON State: CO Zip: 80807

Findings:

15 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|----------------|--------------|----------------------|---------|
| Shalberg, Greg | 719-688-3547 | gregshalberg@aol.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------|-------------|
| 208128 | WELL | PR | 03/01/2025 | GW | 017-07063 | NORRENE 13-2 1 | PR |

General Comment:

This is a field audit of the scout card, related documents and the location conducted by SE Compliance Specialist Brian Welsh

Location

| | | | |
|--------------------|-------------------------------|-------|--|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Dirt road through farm ground | | |
| Corrective Action: | | Date: | |

Overall Good:

| | | | |
|----------------------|--------------------------|-------|--|
| Signs/Marker: | | | |
| Type | OTHER | | |
| Comment: | Lease sign by meter run | | |
| Corrective Action: | | Date: | |
| Type | CONTAINERS | | |
| Comment: | Sticker on chemical drum | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | Lease sign by compressor | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Metal sign by tank | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------------|--|-------|-------|
| Emergency Contact Number: | | | |
| Comment: | | | |
| Corrective Action: | | Date: | _____ |

| | | | |
|---------------------------|---|-------|------------|
| Good Housekeeping: | | | |
| Type | OTHER | | |
| Comment: | Stained soil at prime mover | | |
| Corrective Action: | Conduct maintenance on equipment, cleanup stained material and review self inspection processes | Date: | 10/18/2025 |

Overall Good:

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment: _____

Multiple Spills and Releases?

| | | | |
|--------------------------|---|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Prime Mover | # 1 | | |
| Comment: | Arrow gas engine | | |
| Corrective Action: | | Date: | |
| Type: Vertical Separator | # 1 | | |
| Comment: | Vertical gas separator east of wellhead | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------------|--|--|-------|
| Type: Pump Jack | # 1 | | |
| Comment: | American 114 | | |
| Corrective Action: | | | Date: |
| Type: Gas Meter Run | # 1 | | |
| Comment: | Meter run south of wellhead on north side of CR Z | | |
| Corrective Action: | | | Date: |
| Type: Ancillary equipment | # 6 | | |
| Comment: | Gas scrubber, chemical tank, telemetry equipment at meter run, propane tanks, cathodic generator and rectifier | | |
| Corrective Action: | | | Date: |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---------------------------------------|----------|-----------|---------|-----------------------|
| CRUDE OIL | 1 | 300 BBLs | STEEL AST | | 38.948930,-102.201620 |
| Comment: | Tank is on the south side of wellhead | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | |
|------------------|--|
| Condition | |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|---|---------------------|---------------------|-------------|
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | Berms will need maintenance for capacity. Dirt piles are on location for berm repairs | | | |
| Corrective Action: | | | | Date: |

Venting:

| | |
|--------------------|-------|
| Yes/No | |
| Comment: | |
| Corrective Action: | Date: |

Flaring:

| | |
|--------------------|-------|
| Type | |
| Comment: | |
| Corrective Action: | Date: |

Inspected Facilities

Facility ID: 208128 Type: WELL API Number: 017-07063 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing. Meter run is 1650' SSW of wellhead](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|---------|
| Compaction | Pass | Compaction | Pass | Material Handling And Spill Prevention | Pass | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 404360926 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7244500 |
| 715202982 | location photo | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7244494 |
| 715202983 | meter run | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7244495 |