

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/19/2025

Submitted Date:

09/19/2025

Document Number:

716301525

FIELD INSPECTION FORM

Loc ID: 307381 Inspector Name: Beardslee, Tom On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10758
Name of Operator: OGRIS OPERATING LLC
Address: PO BOX 53467
City: MIDLAND State: TX Zip: 79710

Findings:

- 9 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|---------------|--------------|-------------------|---------------------------------|
| BACA, DAVE | 719-859-4066 | dbaca@ogrisop.com | All Inspections |
| B WARD, GIENA | | gward@ogrisop.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------|-------------|
| 217572 | WELL | PR | 09/12/2007 | CBM | 071-06350 | HILL RANCH 32-5 | PR |

General Comment:

"This is a field audit of the scout card, related documents and the location."

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

| | | | |
|--------------------|--|--|------------------|
| Type | WEEDS | | |
| Comment: | PHOTO 3: TREE GROWING OVER THE TOP OF ELECTRICAL PANEL AND VEGETATION AROUND WELLHEAD AND METER HOUSE. | | |
| Corrective Action: | REMOVE TREE ON LOCATION AND MAINTAIN WEEDS AROUND ALL EQUIPMENT ON LOCATION PER RULE 606. | | Date: 10/19/2025 |

Overall Good:

| Spills: | | | |
|----------------|------|--------|--|
| Type | Area | Volume | |
| | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

| Equipment: | | | corrective date |
|---------------------------|---|--|-----------------|
| Type: Vertical Separator | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Progressive Cavity | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Deadman # & Marked | # 4 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Bradenhead | # 1 | | |
| Comment: | IS ACCESSABLE | | |
| Corrective Action: | | | Date: |
| Type: Gas Meter Run | # 1 | | |
| Comment: | CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR. | | |
| Corrective Action: | | | Date: |
| Type: Ancillary equipment | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

| Venting: | | | |
|-----------------|----|--|--|
| Yes/No | NO | | |
| Comment: | | | |

| | | | |
|--------------------|--|-------|--|
| Corrective Action: | | Date: | |
|--------------------|--|-------|--|

Flaring:

| | | | |
|--------------------|--|-------|--|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Inspected Facilities

Facility ID: 217572 Type: WELL API Number: 071-06350 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 11/26/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: METER WILL NEED ANNUAL CALIBRATION ON OR BEFORE 11/26/2025

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction | Pass | Compaction | Pass | | | |
| Gravel | Pass | Gravel | Pass | | | |

Comment:
 Corrective Action: Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: NO Pit ID: 258336 Lat: _____ Long: _____
 Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:
 Liner Type: _____ Liner Condition: _____
 Comment:
 Corrective Action Date: _____

Fencing:
 Fencing Type: None Fencing Condition: _____
 Comment:
 Corrective Action Date: _____

Netting:
 Netting Type: _____ Netting Condition: _____
 Comment:
 Corrective Action Date: _____
 Anchor Trench Present: NO Oil Accumulation: NO 2+ feet Freeboard: YES
 Comment:
 Corrective Action Date: _____

ECMC Comments

| Comment | User | Date |
|---|----------|------------|
| <p>ECMC Inspection Report Summary On Tuesday 9-19-2025 at approximately 13:15, I Tom Beardslee Conducted an on-site inspection an Evergreen Natural Resources location HILL RANCH 32 -5 API# 05-071-06350 in Las Animas County Colorado. While there, I observed production operation. During this inspection the following possible compliance issues were observed: PHOTO 3: TREE GROWING OVER THE TOP OF ELECTRICAL PANEL AND VEGETATION AROUND WELLHEAD AND METER HOUSE. REMOVE TREE ON LOCATION AND MAINTAIN WEEDS AROUND ALL EQUIPMENT ON LOCATION PER RULE 606. CA DATE 10/19/2025. A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules.</p> | beardslt | 09/19/2025 |

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------------|---|
| 404361349 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7244950 |
| 716301526 | INSP. PHOTOS | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7244945 |