

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/17/2025

Submitted Date:

09/19/2025

Document Number:

717300485

FIELD INSPECTION FORM

Loc ID 318445 Inspector Name: Maclaren, Joe On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1700 LINCOLN ST STE 4550
City: DENVER State: CO Zip: 80203

Findings:

- 6 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Watzman, Ross		rwatzman@kpk.com	
Burn, Diana		diana.burn@state.co.us	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Case, Dustin		dcase@kpk.com	
Silver, Randy		randy.silver@state.co.us	
Clark, Lily		lclark@kpk.com	
McCoy, Diane		diane.mccoy@state.co.us	
		cogcc@kpk.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241306	WELL	PR	01/01/2024	OW	123-09095	UPRR 43 PAN AM I 26	PA

General Comment:

ECMC Engineering Integrity Inspection
FLIR & RMLD Surveys Performed
Well has been Plugged and Abandoned
Photo Log Uploaded

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Electrical service/ meter observed on location.		
Corrective Action:	Comply with ECMC rule 606 - remove unused equipment.	Date:	10/20/2025
Type	TRASH		
Comment:	Concrete debris, well casing pipe cut off, electrical service trash, pipe/ fencing debris observed on location.		
Corrective Action:	Comply with ECMC rule 606 - remove trash from location.	Date:	10/20/2025
Type	WEEDS		
Comment:	Excessive weed growth observed on location.		
Corrective Action:	Comply with ECMC rule 606 - remove & control weed growth.	Date:	10/20/2025

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type: Flow Line	#		corrective date
Comment:	No flowlines/ flowline risers observed in PA well excavation or location.		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 241306 Type: WELL API Number: 123-09095 Status: PR Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

