

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/15/2025

Submitted Date:

09/19/2025

Document Number:

718300062

**FIELD INSPECTION FORM**

Loc ID 329958 Inspector Name: Anderson, Laurel On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 100322  
Name of Operator: NOBLE ENERGY INC  
Address: 1099 18TH STREET SUITE 1500  
City: DENVER State: CO Zip: 80202

**Findings:**

- 5 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Brown, Kari		kari.oakman@state.co.us	
, Inspections		rbucogccinspectionreports@chevron.onmicrosoft.com	<a href="#">All Chevron Inspections</a>
Graber, Nikki		nikki.graber@state.co.us	
Peterson, Dan		danpeterson@chevron.com	
Mitchem, Katelyn		katelyn.mitchem@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
250292	WELL	PA	06/21/2022	GW	123-18095	HSR-GUTTERSEN 10-3	PA
329958	LOCATION	AC			-	HSR-GUTTERSEN-63N64W 3NWSE	EI
490402	TANK BATTERY	AC	06/06/2025		-	HSR GUTTERSEN 490402	EI
491272	SPILL OR RELEASE	AC			-	HSR Guttersen-63N64W 3NWSE	EI
491273	SPILL OR RELEASE	AC			-	HSR Guttersen-63N64W 3NWSE	EI
491274	SPILL OR RELEASE	AC			-	HSR Guttersen-63N64W 3NWSE	EI

**General Comment:**

This is an ECMC Environmental Field Inspection to determine progress on Spill IDs 491272, 491273, 491274 and Remediation Project #41603. Any corrective actions from previous inspections, NOAVs and/or conditions of approval from previous forms that have not been fully addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Spill IDs 491272, 491273, 491274, REM 41603  
Spill Name: HSR Gutttersen-63N64W 3NWSE  
Spill ID: 491272  
Impacts discovered at Separator Riser and DL  
Reported Date of Discovery: 08/25/2025

Spill Name: HSR Gutttersen-63N64W 3NWSE  
Spill ID: 491273  
impacts discovered at AST01  
Reported Date of Discovery: 08/25/2025

Spill Name: HSR Gutttersen-63N64W 3NWSE  
Spill ID: 491274  
Impacts discovered at PWV  
Reported Date of Discovery: 08/25/2025

Remediation Project No: 41603  
Tank Battery Facility ID: 490402  
Location ID: 329958

Date of Inspection: 09/15/2025  
Weather: Partly Cloudy, 84°F

Current site status:

- Signage with emergency contact number is present near the 3rd party meter shed remaining on location.
- The tank battery has been decommissioned.
- The excavation associated with the removal of the produced water vessel (sample locations PWV01@5' & PWV01-SS01@4') that was visible in photo documentation attached to Form 19i Doc #404331271 and associated with Spill ID 491274 was not observed during ECMC's inspection and appear to have been backfilled to grade.
- Stained soil visible in photo documentation attached to Form 19i Doc #404331131 for Spill ID 491273 at the AST01@0.5' sample location was not observed during ECMC's inspection.
- The excavations associated with soil sampling at the separator flowline riser (SEP01-FLR@3') and dumpline (SEP01-DL@3') that were visible in photo documentation attached to Form 19i Doc #404330892 and associated with Spill ID 491272 were not observed during ECMC's inspection and appear to have been backfilled to grade.
- Weeds observed on location and around the perimeter of the tank battery.
- Flowlines and other equipment have been removed and are being stored in a roll-off dumpster on location.

See attached corrective actions.

**Inspected Facilities**

Facility ID: 250292 Type: WELL API Number: 123-18095 Status: PA Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 329958 Type: LOCATION API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 490402 Type: TANK API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 491272 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 491273 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 491274 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Environmental**

**Spills/Releases:**

Type of Spill: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: Spill ID 491274 was created to address the remediation of impacts identified at the produced water vessel at the tank battery. Spill ID 491273 was created to address the remediation of impacts identified at the crude oil AST at the tank battery. Spill ID 491272 was created to address the remediation of impacts identified at the separator at the tank battery. Remediation Project #41603 was created for decommissioning of the HSR-GUTTERSEN-63N64W3NWSE Location (Location ID 329958) and HSR GUTTERSEN Tank Battery (Facility ID 490402). The tank battery has been decommissioned. The tank battery surface appears to have been recently graded.

Corrective Action: These spill/release reports will remain unresolved until a Supplemental Form 27 is approved under the existing Remediation Project #41603. The Supplemental Form 27 shall include an updated implementation schedule in addition to proposed specific actions to address the identified releases. Quarterly reporting is required for REM 41603. Date: \_\_\_\_\_

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_  
Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**Spill/Remediation:**

Comment: The excavations at the separator riser and dumpline (Spill ID 491272) and former produced water vessel (Spill ID 491274) appear to have been backfilled and the tank battery surface including where soil sample AST01@0.5' was collected (Spill ID 491273) appears to have been recently graded.

Corrective Action: Operator shall provide all waste manifests as required by Rule 905.b.(3) for oily waste hauled off site for disposal. Additionally, Operator shall provide all tickets for material hauled on site for backfill. This documentation shall be included on the next Supplemental Form 19 or 27. Date: \_\_\_\_\_

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_  
 1003c. Compacted areas have been cross ripped? \_\_\_\_\_  
 1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_  
 Cuttings management: \_\_\_\_\_  
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_  
 Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

RESTORATION AND REVEGETATION

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003e. INTERIM VEGETATION TRANSECT  
 TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_  
 TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_  
 TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_  
 VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_ F \_\_\_\_\_

Comment

Corrective Action

Date 10/03/2025

Overall Interim Reclamation Fail

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment:

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

1004.d. FINAL VEGETATION TRANSECT  
 TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_  
 TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_  
 TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_  
 VEGETATIVE COVER \_\_\_\_\_

Comment:

Corrective Action:

Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location  Multi-Well Location

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404360684	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7244067">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7244067</a>
718300063	2025_0915_HSR Guttersen- 63N64W3NWSE Photo Log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7244063">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7244063</a>