

**FORM
INSP**
Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
09/15/2025
Submitted Date:
09/19/2025
Document Number:
718300064

FIELD INSPECTION FORM

Loc ID 430790 Inspector Name: Anderson, Laurel On-Site Inspection 2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:
ECMC Operator Number: 69175
Name of Operator: PDC ENERGY INC
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

Findings:
9 Number of Comments
5 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Dunnam, Anthony		anthony.dunnam@state.co.us	
Graber, Nikki		nikki.graber@state.co.us	
PDC, Legacy		rbucogccinspectionreports@chevron.onmicrosoft.com	All Legacy PDC Inspections
Peterson, Dan		danpeterson@chevron.com	
Brown, Kari		kari.oakman@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
430790	LOCATION	AC			-	Campbell JF PAD 17-41D	EI
430904	WELL	TA	06/25/2024	OW	123-36324	Campbell JF 17-41D	TA
460607	TANK BATTERY	AC	01/10/2019		-	Campbell JF PAD /17-41D battery	EI
491381	SPILL OR RELEASE	AC	09/17/2025		-	Campbell JF PAD 17-41D	EI

General Comment:

This is an ECMC Environmental Field Inspection to determine progress on Spill ID 491381 and Remediation Project #33091. Any corrective actions from previous inspections, NOAVs and/or conditions of approval from previous forms that have not been fully addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Campbell JF PAD 17-41 (Location ID 430790)
Campbell JF PAD 17-41D battery (Facility ID 460607)
Campbell JF 17-41D Well (API 123-36324)
Spill Name: Campbell JF PAD 17-41
Spill ID: 491381

Spill Details: On 9/9/2025, the potential presence of impacted material(s) was identified via hydrocarbon odor and hydrocarbon staining during decommissioning activities at the Campbell JF PAD 17-41D, tank battery, sample: SEP03-DL, located at the separator dumpline. The volume of potentially impacted material(s) is not currently known.
Reported Date of Discovery: 9/9/2025
Remediation Project #33091

Date of Inspection: 09/15/2025
Weather: Partly Cloudy, 84°F

Current site status:

- The excavation associated with soil sampling at the separator dumpline (SEP03-DL@5') and visible in photo documentation attached to Form 19i Doc #404348902 and associated with Spill ID 491381 was not observed during ECMC's inspection and appears to have been backfilled to grade.
- Signage at Campbell 17-41D wellhead is inadequate (See Photo 6)
- Cattle fencing is installed around the Campbell 17-41D wellhead and is adequate (See Photo 6)
- The tank battery has been decommissioned; 3rd party meter shed remains on location (See Photo 5)
- Weeds are present around the perimeter of the location and along the lease road (See Photos 1-6)
- Portable restroom on location has toppled over (See Photo 1)

See attached corrective actions.

Location

Overall Good:

Signs/Marker:

Type	BATTERY		
Comment:	No signage was observed at the former tank battery.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Signage present at Campbell JF 17-41D Well does not include the API number (API 123-36324) and is difficult to read from a distance.		
Corrective Action:	Install sign to comply with Rule 605.d. By CA due date unless well is cut and capped beforehand.	Date:	12/19/2025

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	<input type="text"/>
Corrective Action:	<input type="text"/>		

Good Housekeeping:

Type	OTHER		
Comment:	Portable restroom on location has toppled over (See Photo 1).		
Corrective Action:	Remove or upright and secure portable toilet using tie-downs or stake-downs as needed. Conduct self-inspection, maintenance, and good housekeeping procedures and schedules in accordance with Rule 1002.f.(2).D	Date:	10/03/2025

Overall Good:

Spills:

Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	Fencing is adequate. Cattle fencing has been installed around the Campbell JF 17-41D Well (API 123-36324).		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 430790 Type: LOCATION API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 430904 Type: WELL API Number: 123-36324 Status: TA Insp. Status: TA

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 460607 Type: TANK API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 491381 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Environmental

Spills/Releases:

Type of Spill: _____ Estimated Spill Volume: _____

Comment: **Spill ID 491381 was created to address the remediation of impacts identified at the separator dumpline (SEP03-DL@5'). Remediation Project #33091 was created for decommissioning of the Campbell JF PAD 17-41 (Location ID 430790) including the Campbell JF PAD 17-41D battery (Facility ID 460607), Campbell JF 17-41D Well (API 123-36324) and associated off-location flowline.**

Corrective Action: **This spill/release report will remain unresolved until a Supplemental Form 27 is approved under the existing Remediation Project #33091. The Supplemental Form 27 shall include an updated implementation schedule in addition to proposed specific actions to address the identified release. Quarterly reporting is required for REM 33091.**

Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____ Comment: _____

Spill/Remediation:

Comment: **The excavation associated with soil sampling at the separator dumpline (SEP03-DL@5') and visible in photo documentation attached to Form 19i Doc #404348902 and associated with Spill ID 491381 was not observed during ECMC's inspection and appears to have been backfilled to grade.**

Corrective Action: **Operator shall provide all waste manifests as required by Rule 905.b.(3) for oily waste hauled off site for disposal. Additionally, Operator shall provide all tickets for material hauled on site for backfill. This documentation shall be included on the next Supplemental Form 19 or 27.**

Date: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: IRRIGATED

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____
 1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____ F _____

Comment Weeds are present around the perimeter of the location and along the lease road (See Photos 1-6)

Corrective Action Comply with Rules 606.c. and 1003.f.

Date 10/03/2025

Overall Interim Reclamation Fail

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: IRRIGATED

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404360685	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7244069
718300065	2025_0915_Campbell JF PAD 17-41 Photo Log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7244064