

# Inspection Photos

09/17/2025

**Operator:** TEP Rocky Mountain LLC #96850

**Location ID:** 335209

**Inspection Doc:** 719200247

Garfield County, CO

Emily Gaasche  
NW Reclamation Specialist  
ECMC



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335209



**Photo 1:** Photos showing an overview of the location looking north and southwest, respectively.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335209



**Photo 2:** Photos showing an overview of the location looking east and west, respectively.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335209



**Photo 3:** A corner of the secondary liner is not sufficiently impervious to prevent a spill or release. Comply with Rule 603.o.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335209



**Photo 4:** Photos showing an overview of the southeastern interim areas. Some portions of the interim areas are predominantly bare with little to no plant establishment. These areas are not progressing towards 1003 reclamation requirements.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335209



**Photo 5:** Photos showing an overview of the western interim area. Some portions of the interim areas are predominantly composed of undesirable plant species. These areas are not progressing towards 1003 reclamation requirements. Conduct additional 1003 reclamation efforts.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335209



**Photo 6:** Photos showing an overview of the southern interim areas. Some portions of the interim areas are predominantly bare with little to no plant establishment. These areas are not progressing towards 1003 reclamation requirements. Conduct additional 1003 reclamation efforts.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335209



**Photo 7:** Photos showing an overview of the southern interim area above the cut slopes. Big sagebrush has established; however, establishment does not appear to be uniform throughout the interim areas.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335209



**Photo 8:** Photos showing a stormwater control on the northern portion of the site is in disrepair, and erosion and sediment transportation is occurring. Stormwater BMP's appear to be missing or insufficient; comply with Rule 1002.f.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources