

Inspection Photos

Location Name: R. MILLER-67N64W/24NWSW

Location #: 306145



Photo #1

R. Miller 13-24, 23-24 Battery site

Inactive | Shut-down

Equipment documented: Loc. ID 306145



Photo #2

R. Miller 13-24, 23-24 Battery site

Inactive | Shut-down

Wellsite(s), Battery entrance



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: R. MILLER-67N64W/24NWSW

Location #: 306145



Photo #3

R. Miller 13-24, 23-24 Battery site

Inactive | Shut-down

Crude oil, produced H2O tank(s), vault(s): SE corner



Photo #4

R. Miller 13-24, 23-24 Battery site

Inactive | Shut-down

Crude oil, produced H2O tank(s), vault(s)

CA: Overgrown vegetation



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: R. MILLER-67N64W/24NWSW

Location #: 306145



Photo #5

R. Miller 13-24, 23-24 Battery site

Inactive | Shut-down

ECD(s), Separator(s)

CA: Overgrown vegetation



Photo #6

R. Miller 13-24, 23-24 Battery site

Inactive | Shut-down

Battery signage



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Location Name: R. MILLER-67N64W/24NWSW

Location #: 306145

Associated Well(s)	Location	API	Status
1. R. Miller 13-24	306145	123-24057	SI
2. R. Miller 23-24	306146	123-24058	SI

Photo #7

R. Miller 13-24, 23-24 Battery site

Inactive | Shut-down

Associated Well(s)

2: Shut-In | SI



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources