

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/24/2025

Submitted Date:

09/28/2025

Document Number:

719700142

FIELD INSPECTION FORM

Loc ID 305808 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 69175
Name of Operator: PDC ENERGY INC
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

Findings:

16 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-------|---|---------------------------------|
| , | | rbucogccinspectionreports@c hevron.onmicrosoft.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|----------|--------|-------------|------------|---------|-----------------------------|-------------|
| 305808 | LOCATION | AC | | | - | PAPPENHEIM-67N64W 24SWNW | IO |

General Comment:

*This is an audit of the scout card and related documents followed by a field audit.

| Location | | | |
|--|---|--------|-----------------|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Adequate | | |
| Corrective Action: | | Date: | |
| Overall Good: <input type="checkbox"/> | | | |
| Signs/Marker: | | | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | OOSLAT applied at separator. | | |
| Corrective Action: | | Date: | |
| Type | BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Emergency Contact Number: | | | |
| Comment: | Posted. | | |
| Corrective Action: | | | Date: _____ |
| Overall Good: <input type="checkbox"/> | | | |
| Spills: | | | |
| Type | Area | Volume | |
| In Containment: No | | | |
| Comment: | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | |
| Fencing/: | | | |
| Type | IGNITOR/COMBUSTOR | | |
| Comment: | Iron panel. | | |
| Corrective Action: | | Date: | |
| Type | TANK BATTERY | | |
| Comment: | Braided wire. | | |
| Corrective Action: | | Date: | |
| Type | SEPARATOR | | |
| Comment: | Braided wire. Surrounded by earth berms. | | |
| Corrective Action: | | Date: | |
| Equipment: | | | |
| Type: Gas Meter Run | # 1 | | corrective date |
| Comment: | Gas Sales, Master; (Phillips 66). Calibration card(s) indicates calibration <= 1 year. Last calibration: 09/02/2025. Inactive. | | |
| Corrective Action: | | Date: | |
| Type: Bird Protectors | # 2 | | |
| Comment: | | | |

| | | | |
|-----------------------------------|---|-------|--|
| Corrective Action: | | Date: | |
| Type: Horizontal Heated Separator | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Emission Control Device | # 1 | | |
| Comment: | Crude oil storage vapor line combustor(s). Controls crude oil storage vapors. Pilots: OFF. Shut-down. | | |
| Corrective Action: | | Date: | |
| Type: Ancillary equipment | # 1 | | |
| Comment: | Battery site: 1: ECD scrubber(s). | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|--|----------|---------------------|---------|--------|
| | | | CENTRALIZED BATTERY | | |
| Comment: | Centralized Battery serves 3 Location IDs (305806, 305807, 305808). (Well(s): 3: Shut-In SI). Centralized Battery serves 1 Tank Battery Facility ID (Pending). | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | |
|------------------|--|
| Condition | |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| | | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|-----------------------|
| CRUDE OIL | 1 | 300 BBLs | STEEL AST | | 40.561164,-104.505511 |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | |
|------------------|----------|
| Condition | Adequate |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|-------|----------|---------------------|---------------------|-------------|
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate |

| | | | | | | | |
|---|----------|---------------------|---------------------|-------------|--------|-------|--|
| Comment: Berms shared w/ crude oil, produced H2O tank(s). | | | | | | | |
| Corrective Action: | | | | | | Date: | |
| Contents | # | Capacity | Type | Tank ID | SE GPS | | |
| PRODUCED WATER | 1 | 100 BBLs | PBV FIBERGLASS | | , | | |
| Comment: | | | | | | | |
| Corrective Action: | | | | | | Date: | |
| Paint | | | | | | | |
| Condition | | | | | | | |
| Other (Content) | | | | | | | |
| Other (Capacity) | | | | | | | |
| Other (Type) | | | | | | | |
| Berms | | | | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | | | |
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate | | | |
| Comment: Berms shared w/ crude oil, produced H2O tank(s). | | | | | | | |
| Corrective Action: | | | | | | Date: | |
| Wells Served By Facilities Above | | | | | | | |
| API Number | | | AirsID | | | | |
| 123-23509 | | | API Number | | AirsID | | |
| 123-23507 | | | | | | | |
| 123-23508 | | | | | | | |
| Venting: | | | | | | | |
| Yes/No | NO | | | | | | |
| Comment: | | | | | | | |
| Corrective Action: | | | | | | Date: | |
| Flaring: | | | | | | | |
| Type | | | | | | | |
| Comment: | | | | | | | |
| Corrective Action: | | | | | | Date: | |

Inspected Facilities

Facility ID: 305808 Type: LOCATION API Number: - Status: AC Insp. Status: IO

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

| Reclamation - Storm Water - Pit | | | | | | |
|--|-----------------|-------------------------|-----------------------|---------------|--------------------------|-------------|
| Storm Water: | | | | | | |
| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
| Gravel | Pass | Gravel | Pass | | | |
| Comment: <input style="width: 90%;" type="text"/> Corrective Action: <input style="width: 90%;" type="text"/> | | | | | | Date: _____ |
| Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT | | | | | | |

| ECMC Comments | | |
|---|--------|------------|
| Comment | User | Date |
| <p>This is a BATTERY audit. Well(s): 3: Shut-In SI. Battery: Inactive Shut-down.</p> <p>Centralized Battery serves 3 Location IDs (305806, 305807, 305808). (Well(s): 3: Shut-In SI).</p> <p>Centralized Battery serves 1 Tank Battery Facility ID (Pending).</p> <p>Reference (Associated Well(s), Battery / Facility Audits): A.) Field Audit Report doc. #719700136 and/or Location ID #305808 for SI Well(s) info. B.) Field Audit Report doc. #719700138 and/or Location ID #305806 for SI Well(s) info. C.) Field Audit Report doc. #719700140 and/or Location ID #305807 for SI Well(s) info. D.) Field Audit Report doc. #719700142 and/or Location ID #305808 for Battery / Facility, Equipment info.</p> | evinsb | 09/28/2025 |
| <p>CECMC Audit Report Synopsis:</p> <p>On WED 09/24/2025 at approximately 17:11 hrs. I, Bret Evins, conducted an onsite audit at: Operator Name: PDC ENERGY INC Facility Name: Pending Facility ID: Pending Location Name: PAPPENHEIM-67N64W/24SWNW Location ID: 305808 Well Name(s): See photo(s) #6 attached to this report. API: See "Wells Served By Facilities Above" sec on pg. 4 and/or photo(s) #6 attached to this report. Location County: Weld County, Colorado Weather: Mostly Sunny, wet from prior storm.</p> <p>While there, I observed: Well(s): 3: Shut-In SI. Battery: Inactive Shut-down.</p> <p>Routine audit.</p> <p>*Any Corrective Actions from prior audits that have not been addressed remain applicable.</p> | evinsb | 09/28/2025 |

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------|---|
| 719700143 | Audit photo(s) | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7257711 |